

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6468)

-----  
Set post cor. of secs. 26, 27, 34 and 35, from which  
A B.Oak 10" dia., bears N.30°W., 75 lks. dist.  
A B.Oak 18" dia., bears N.72°E., 87 lks. dist.  
A B.Oak 12" dia., bears S.54°W., 69 lks. dist.  
A Pine 18" dia., bears S.37°E., 48 lks. dist.

GL0 survey by W.H. Byars under Contract #152 dated June 3, 1871 (DCSO records Vol. 15 Page(s) 6491)

-----  
Established cor. to secs. 26, 27, 34 and 35, from which  
A Fir 6" dia., bears N.20°E., 21 lks. dist.  
A Fir 12" dia., bears S.52°E., 17 lks. dist.  
A Fir 6" dia., bears S.20°W., 16 lks. dist.  
A maple 6" dia., bears N.75°W, 17 lks. dist.

Survey by Frank Cain - For: J.F. Pefley; Hyman Huntley and J.M. Ledgerwood, chainmen. - Nov. 10, 1913 - Field Book 33 Page 16

-----  
Rotten and marking dim a Fir post 3½" x 36", from which  
A Fir 8" dia., bears N.12°30'E., 22 lks.  
A Fir 18" dia., bears N.59°45'W., 48½ lks.  
A Fir 24" dia., bears S.79°20'W., 62 lks.  
A Fir 16" dia., bears S.53°40'E., 84 lks.

Survey by John H. Markham Jr. - Wit: Wm. & Geo. Vaughn - For: Stomar Lumber Co. - March 17 & 18, 1951 - C.S. File 40/294

-----  
All of the renewed BTs blown down except  
A Fir 24" dia., bears S.54°E., 55.5 ft.  
At corner point Set 1" x 24" Iron pipe, from which  
A Fir 40" dia., bears N.10°W., 32.0 ft. mkd. S27 BT.  
A Fir 7" dia., bears S.6°E., 14.3 ft. mkd. S34 BT.

Cadastral survey by Hans W. Thielsen and C. Albert White under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug. 5, 1959 (DCSO records Vol. 30 Page(s) 12814-15)

-----  
From the sec. cor., perpetuated with an iron pipe, 1" dia., 8" above ground, firmly set. This cor. was first established by Ford in 1854, reestablished by Byars in 1872. The Douglas County Records show that Roberts, Deputy Co. Surveyor (under Cain) renewed the cor., in 1903 (?) (F.B. says 1913), with new bearing trees.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

John Markham renewed the cor. in 1951 with the above described iron pipe and marked two new BTs.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. dia., 20 ins. in the ground, with brass cap mkd:

T 29 S R 6 W  
S 27 | S 26  
S 34 | S 35  
1958

from which trees marked by Roberts in 1903:

A Fir 24" dia., bears S.53½°E., 84 lks. dist. mkd. with healed blaze.

A Fir 28" dia., dead and fallen, bears S.79¼°W., 62 lks. dist. mkd. with healed blaze.

A Fir 22" dia., dead and fallen, bears N.59½°W., 48½ lks. dist., mkd. with healed blaze.

and trees marked by Markham in 1951:

A Fir 9" dia., bears S.6°E., 22 lks. dist. mkd. with healed blaze.

A Fir 44" dia., bears N.10°W., 48½ lks. dist. mkd. with healed blaze.

and new bearing trees:

A Fir 24" dia., bears N.69°E., 76½ lks. dist. mkd. T29S R6W S26 BT.

A Fir 7" dia., bears S.32¼°W., 32½ lks. dist. mkd. BT only, at base.

Bury the iron pipe alongside the iron post.

BLM rehabilitation of certain corners, Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech., under Group #2000, Surveyed April/June 2002, - (DCSO records Vol. 54 Page(s) 21133-4)

-----  
The cor. of secs. 26, 27, 34, and 35, monumented with an iron post, 2½ ins. diam., firmly set, projecting 5 ins. above ground, (with an iron pipe, 1 in. diam., firmly set, flush with the ground, alongside,) with brass cap (properly) mkd. from which bearing trees mkd. by John H. Markham, Jr., in 1951, and reported by Thielsen and White

A fir, 22" dia., bears S.6°E., 14.5 ft., with no marks visible.

A fir, 40" dia., bears N.10°W., 32.0 ft., with no marks visible.

and the remains of a bearing tree mkd. by Thielsen and White

A decayed & sawed fir stump, 23 ins. diam., bears N.69°E., 52.0 ft., with scribe marks B 29S R6W S26 BT visible open blaze. (Record, 50.5 ft.)

continued next page

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and new bearing trees  
A fir, 8" dia. bears N.87¾°E. 27.1 ft. mkd.T29S R6W S26 BT  
A fir, 12" dia. bears S.13°W. 30.6 ft. mkd.T29S R6W S34 BT  
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.  
Corner is located 1.5 ft. south of the cor. of woven wire fences, extending North and East.  
The geographic position (NAD 1983 (CORS)) of this cor. as determined by NAVSTAR GPS, utilizing dual frequency, carrier phase GPS receivers, (Trimble 5700), relative to the National Spatial Reference System, is as follows:  
Latitude: 43°00'48.23"N. Longitude: 123°23'08.12"W.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24008)  
-----  
The cor. of secs. 26, 27, 34, and 35, reported by Moore and Browning in 2002, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with a brass cap (properly) mkd.  
from which the bearing trees reported by Moore and Browning  
A fir, 11" dia., bears N.87¾°E., 27.1 ft., with a healed blaze.  
A fir, 26" dia., bears S.6°E., 14.5 ft., with a healed blaze.  
A fir, 15" dia., bears S.13°W., 30.6 ft., with a healed blaze.  
A fir, 44" dia., bears N.10°W., 32.0 ft., with a healed blaze.  
Corner is located alongside a fence cor., with wire fences extending N. and E.  
NAD 1983 (2011)  
Latitude: 43°00'48.24" N. Longitude: 123°23'08.12" W.