

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500242

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 27 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under Contract #152 dated June 3, 1871 (DCSO records Vol. 15 Page(s) 6491-92)

Set ¼ sec. post, from which
A Cedar 6" dia., bears S.45°E., 17 lks. dist.
A Fir 40" dia., bears S.10°W., 26 lks. dist.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: Wm. & George Vaughn - March 17,18, 1951 - C.S. File
40/294

Both O.B.Ts standing.
A Fir 50" dia., bears S.10°W., 16.5 ft. dist.
A Cedar 7" dia., bears S.40°E., 12.0 ft. dist.
At Corner point Set 1" x 24" Iron pipe, from which
A Yewwood bears S.52°E., 22.5 ft. mkd. ¼ S, BT.

Cadastral survey by Hans W. Thielsen and C. Albert White
under Group #s 348 and 350. Surveyed, July 23, 1958 to Aug.
5, 1959 (DCSO records Vol. 30 Page(s) 12815)

The ¼ sec. cor. of sec. 27, determined at record bearing and
distance from the original bearing trees mkd. by Byars in
1872:

A Cedar 8" dia., bears S.45°E., 17 lks. dist. mkd. S on
partly open blaze.
A Fir 45" dia., bears S.10°W., 26 lks. dist. mkd. ¼ S BT
on bark blaze.

At the corner point
Set an iron post, 28 ins. long, 2½ ins. dia., 20 ins. in the
ground, with brass cap mkd:

	¼	
S	27	
T	29	S
R	6	W
	1958	

from which new bearing trees
A Fir 21" dia., bears N.21°E., 43 lks. dist., mkd. BT only
at base.
A Fir 33" dia., bears S.30½°W., 43 lks. dist., mkd. ¼ S27
BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones and
W. Penley - July 1969 - C.S. File 49/139-124

Found - Cadastral brass cap at ¼ corner, properly mkd. in
1958
30" D.Fir now 38", S.30°W., 28.4 ft. scribe visible.
(Cont. Next Page)

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500242

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 27 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>50" D.Fir now 46" S.10°W., 17.2 ft. (Rec. 16.5 ft.) bark scribed ¼S BT. 1" Iron pipe in mound of stone. New BT - 14" Maple N.53°W., 53.2 ft. mkd. ¼ S27 CS BT. This corner will lie by new N-S fence line now being constructed.</p>
<p>Survey by Howard Johnstone - For: Roseburg Lumber Co. - April 1978 - RM 3-12 ----- Found - 1958 Cadastral brass cap and I.P. 38" Fir S.30°W., 28.4 ft. 50" Fir S.10°W., 17.2 ft. 14" Maple N.53°W., 53.2 ft. No new monument or accessories. Corner is 119.72 ft., N.1°02'24"E. of ¼ cor. Sec. 26 only.</p>
<p>BLM Resurvey by Wayne L. Rogers and Bryan S. Seibold, Cadastral Surveyors, under Group #1517, surveyed April/Aug. 1990 - (DCSO records Vol. 50 Page(s) 19190-91) ----- The 1/4 sec. cor. of sec. 27 only, monumented with an iron post, 2½ ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd. in 1958. from which the remains of a bearing tree mkd. by Byars A root hole, bears S. 10° W., 26 lks. dist., with uprooted fir lying alongside, no marks visible. and the remains of a bearing tree mkd. by Thielsen and White A root hole, bears S. 30½° W., 43 lks. dist., with uprooted fir lying alongside, with fragmentary scribe marks visible on partially healed blaze. and a bearing tree mkd. by Powell, in 1969 A maple, 14 ins. diam., bears N. 13° W., 84 lks. dist., with healed double blaze. and a new bearing tree A fir, 5 ins. diam., bears S. 3½° W., 70½ lks. dist., mkd. 1/4 S27 BT.</p>
<p>BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24009) ----- The ¼ sec. cor. of sec. 27 only, reported by Rogers and Seibold in 1990, monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd. from which the remains of the BTs reported by Rogers and Seibold Continued next page</p>

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500242

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 27 only

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A fir, 22" dia., bears S.3½°W., 46.5 ft., with a healed blaze.

A roothole bears S.10°W., 17.2 ft., alongside of which is an uprooted, decayed fir stump, 50" dia., no marks visible. (Original)

A roothole bears S.30½°W., 28.4 ft., alongside of which is a down decayed fir, 33" dia., no marks visible.

A maple, 19" dia., bears N.13°W., 60.2 ft., with a healed double blaze. (Record, 55.4 ft.)

Corner is located W., 6 ft., of wire fence, extends N. and S.

From this cor., a point established as the ¼ sec. cor. of sec. 27 only, by Markham Jr., in 1951. This point was not correctly positioned and was not utilized for control in this survey, bears N.54°27'25"W., 1.00 ft.; monumented with an iron pipe, 1¼" dia., firmly set, projecting 13" above ground.