

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6470)

Set ¼ sec. post, from which
A B.Oak 24" dia., bears S.70°W., 91 lks. dist.
A W.Oak 8" dia., bears S.36½°E., 108 lks. dist.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Dec. 2-9, 1950 - C.S. File 40/294

Determined by O.B.T., a B.Oak windfall, 36" dia., bears S.70°W., 60.0 ft.
At corner point, set 1" x 30" I.P., 30" in ground, from which
A Fir 10" dia., bears N.58°W., 26.0 ft. marked. ¼ S S 22
2880 BT.
A W.Oak 10" dia., bears S.70°E., 29.0 ft. marked ¼ S S 23
2880 BT.

Fd. OK, by Donald Bentz, April 1983, C.S. 58/282 and M 97-42

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24013-4)

The ¼ sec. cor. of secs. 22 and 23, perpetuated by Markham Jr., in 1950; subsequently perpetuated by person(s) unknown; from original evidence no longer in existence; monumented with an iron pipe, 1" dia., firmly set, projecting 12" above ground, from which the remains of the BTs mkd. by Markham Jr.
An oak, 16" dia., bears S.69½°E., 29.2 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears N.55½°W., 25.5 ft., alongside of which is a broken fragment with illegible scribe marks visible on open blaze.
and a bearing tree mkd. by person(s) unknown
An oak, 17" dia., bears N.78¾°W., 20.8 ft., with a healed blaze.

At the corner point
Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, directly over the iron pipe, with brass cap mkd.

T29S R6W
¼
S 22 | S 23
2019

Corner is located alongside a fence cor., with wire fences extending N., E., and S.75°W.