

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6473)

Set ¼ sec. post, at average dist., from which
A B.Oak 10" dia., bears S.12°E., 31 lks. dist.
A B.Oak 10" dia., bears N.67°W., 26 lks. dist.

G.G. Stewart - Wit: C.M. Malcomb; W.S. Crearer - April 1922 - Vol. 3 Pg. 119; C.S. File 6/13

Set from two original BTs, one fallen and other marks destroyed. Set pointed rock and marked
A 12" B.oak S.26½°W., 60.0 ft.
A 10" W.Oak N.12°W., 22.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - M. Godfrey & S. Bilow, crew - Dec. 27, 1957 - C.S. File 49/52-2

Found - Pointed rock with 1" I.P. alongside.
Stewart's, S.26½°W., 60.0 ft. BT, now down, badly rotted, no scribe marks found.
Stewart's N.12°W., 22.0 ft. BT, rotted stump only, no scribe.
Both bearing trees check for bearings & distances.
New BTs - 11" W.Oak N.30°W., 40.2 ft. scribed ¼ S2 CS BT.
6" W.Oak S.65½°W., 13.4 ft. scribed ¼ S11 CS BT.
This corner visited in April, 1962 and found to be OK.

Mark Heimburger - For: Darrell Gehlsen - 8/2020 - M178-9

Found - Record I.pipe laying near fence corner
6", now 11" W.Oak bears S.67¼°W., 13.4'
11" W.Oak, now down & rotten, bears N.30½°W., 40.0'