

TOWNSHIP 29 RANGE 06 POINT IDENTIFIER # 640240

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Howard Johnstone - For: Roseburg Lumber Co. - April 1978 - RM 3-12

Found - 3/4" Iron Pipe. (Not of record)
8" Cedar S.55°E., 16.9 ft.
6" Cedar S.88°W., 12.0 ft.

No new monument or accessories.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2940, surveyed June/Sept. 2019- (DCSO records Vol. 59 Page(s) 24026-7)

The center ¼ sec. cor. of sec. 25, established by an Administrative Survey conducted by the BLM in 1977; subsequently recovered and utilized for the subdivision of sec. 25 by Johnstone, in 1978; and is accepted as the cor.; monumented with an iron pipe, 1¼" dia., firmly set, projecting 9" above ground, from which the remains of the bearing trees mkd. by the Administrative Survey

A decayed cedar stump, 11" dia., bears S.54½°E., 16.8 ft., with scribe marks BT visible on open blaze.

A cedar, 18" dia., bears S.87¾°W., 12.2 ft., with a healed blaze.

At the corner point Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, directly over the iron pipe, with brass cap mkd.

T29S R6W
C ¼ S 25
2019

and a new bearing tree

A fir, 12" dia., bears S.66½°E., 14.0 ft., mkd. C¼ S25 BT. Corner is located alongside a fence cor., with wire fences extending N. and W.