

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 039050

PRIMARY CORNER DESCRIPTION SW Cor. Wells DLC #39

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Bowman and Burnett, under Contract dated Sept. 1855

Set a post, from which
A W.Oak 30" dia., bears S.25°E., 275 lks.
A W.Oak 24" dia., bears S.41°W., 250 lks.

GL0 survey by Mensch under Instructions dated April 18, 1924 (DCS0 records Vol. 14 Page(s) 5981-82)

Intersect the SW cor. of Claim No. 39 which is an oak post, 4" sq., marked C S at cor. of fences, bearing N., S., and E. Alongside the post, Set an iron post 3 ft. long, 1" dia., 28" in the ground, for cor. No. 5 of Claim No. 39, with brass cap marked:
:DLC 39
S7:AP 5
T29SR7W
1924

from which (the original bearing trees)
A W.Oak 30" dia., bears S.41°W., 248 lks. (not 250 lks) blazes plain.
A W.Oak 40" dia., bears S.26½°E., 276 lks. (not S.25°E., 275 lks.) blazes plain.

Douglas Co. Surveyors Office - Willie Penley; Jack Heritage Aug. 10, 1971 - C.S. File 49/139-143

Found - 1924 GL0 brass cap properly marked.
30" resurvey W.Oak now 40", S.41°W., 163.68 ft. Previously opened, visible scribing.
No trace of SE BT. Gone due to land clearing.
New BT -10" D.Fir N.62°W., 31.2 ft. scribed "DLC 39 AP 5 CS BT"
Corner lies in N-S-E fence corner.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/18/2001 - C.S. File 66/19-14

Found - 1924 GL0 brass cap/iron pipe protrudes 8" out of ground. BC/IP is south 2 ft. from a 3-way fence corner, fence line runs N - S & E.
30" now 36" dia., 15 ft. high rotted W.Oak snag previously opened visible scribing bears S.41°W. (dist. not checked) (rec. S.41°W., 163.7) 0BT
10" now 19" dia., D.Fir with a fully healed double blaze bears N.54½°W., 31.2 ft. (Rec. N.62°W., 31.2 ft.) 1971

continued next page

