

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Greg Lang - May 3, 2004 - C.S. File 65/49-33

Found - 1924 GLO brass cap
14" W.Fir bears S.72½°W., 6.93'. BLM in 1988/89 -
Good condition.
New - 25" D.Fir bears N.53¼°W., 126.0', scribed "¼ S19 BT"
7½" D.Fir bears S.31½°E., 27.64', scribed "¼ S30 BT"
10" W.Fir bears S.88½°E., 89.76', scribed "¼ S19 BT"
Note - Corner lies on a flat bench, North & West of Coarse
Gold Creek.

BLM remonumentation by Timothy J. Moore, Cad. Surveyor under
Group #2000 surveyed April 2006 (DCSO rec Vol 55 pgs 21460-1)

The ¼ sec. cor. of secs. 19 and 30, monumented with an iron
post, 1" dia., firmly set, projecting 3" above the ground,
with brass cap mkd. (cap is rotated 180°)
¼ $\frac{S\ 19}{S\ 30}$
1924
from which the remains of a bearing tree mkd. by Mensch
A sawed fir stump, 23" dia, bears N.10°W., 5.3 ft., with
a healed blaze and tin cap.
from which the remains of a BT mkd. by Weller and Bedell
A stump hole, bears N.72½°W., 6.9 ft., a blown down, 21"
dia fir, lying along side with a healed blaze.
and the remains of bearing trees marked by Lang
A stump hole, bears S.31½°E., 27.6 ft., with a blown down,
8" dia. fir, lying along side, mkd. ¼ S 30 BT.
A stump hole, bears S.88½°E., 89.8 ft., with a blown down,
12" dia. fir, lying along side, mkd. ¼ S 19 BT
A fir, 27" dia, bears N.53¼°W., 126.0 ft., mkd. ¼ S 19 BT.
This tree has been girdled by a cable; it was use as a
tail hold for a logging operation.
and new bearing trees
A fir, 5" dia, bears N.58°W., 13.1 ft., mkd. X BT.
A fir, 7" dia, bears S.67°E., 9.1 ft., mkd. 1/14 S30 BT.
This corner is located in an area where the timber was just
harvested.