

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 200320

PRIMARY CORNER DESCRIPTION S. 1/16 between Sec's 19|20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Subdivision of Section 19, Daniel E. Weller, Dale T. Bedell, Group # 1447. Surveyed June 1988 - Feb. 1989. (DCSO records Vol. 48 Page(s) 18534)

Set a stainless steel post, 28" long. 2½" dia., 23" in the ground with brass cap mkd.

S 1/16
S 19|20
1988

BTs - A Fir, 13" dia. bears N.4½°E., 54 lks. mkd. "S 1/16 S20 BT"

A Fir, 28" dia. bears S.14°W., 67½ lks. mkd. "S 1/16 S19 BT"

Mark Smalley, for Roseburg Forest Products. Oct. 4, 1993. Corner Restoration form in C.S. File 63/153-45

Found - Iron pipe/brass cap good condition, leans north.
BTs - 13" Fir, bears N.4½°E., 54 lks. now 6' tall stump.
30" Fir, bears S.14°W., 67½ lks. good condition, partly healed face.

New Accessories -
8" Fir, bears S.58°W., 39.3 ft. scribed "1/16 BT".

Kris DeGroot - For: Roseburg Resources - 6/2014 - M166-11

Found - A 2½" stainless steel post by BLM Cadastral Surveyors Weller & Bedell in 1988, leaning severely Northerly, disturbed by cat logging, with a ¾" brass cap properly mkd per BLM Record. I excavate and straighten the bent pipe, locate & tie the deep-one magnet, and reset post exactly over the deep-one, projecting 6" above the ground. From which BTs by Weller & Bedell:

A 30" D.Fir bears S.2°30'E., 42.3 ft with healed blaze (S.14°W., 67.5 lks.)

A 10" D.Fir saw snag, 6 ft tall with tin cap, bears N.10°30'W., 34.6 ft with scribe mks "S 1/16 S19 BT" visible on partially healed open blaze (N.4°30'E., 54 lks.)

And a bearing tree by Smalley in 1994 per CS 63/153:

A 13" D.Fir bears S.60°W., 38.7 ft. With healed blaze (S.58°W., 39.3 ft)