

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec Cor for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6543)

-----  
Set a post cor. of secs. 17, 18, 19 and 20, from which  
A Red Fir 18" dia., bears S.42½°E., 12 lks. dist.  
A Red Fir 8" dia., bears N.51°E., 12 lks. dist.  
A Red Fir 14" dia., bears N.47°W., 11 lks. dist.  
A Red Fir 15" dia., bears S.16°W., 14 lks. dist.

GL0 survey by Mensch under Instructions dated April 18, 1924 (DCSO records Vol. 14 Page(s) 5950)

-----  
Intersect the point for cor. of secs. 17, 18, 19, and 20, located by measurement from the original bearing trees; blazes are plain on all these trees, marks overgrown and not opened.

At the exact cor. point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor., with brass cap marked:

T29S	R7W
S18	S17
S19	S20
1924	

from which the original bearing trees:

- A Fir 40" dia., bears N.51°E., 12 lks. dist.
- A Fir 14" dia., bears S.42½°E., 12 lks. dist.
- A Fir 24" dia., bears S.16°W., 14 lks. dist.
- A Fir 30" dia., bears N.47°W., 11 lks. dist.

New Bearing trees:

- A Cedar 14" dia., bears N.24½°E., 84 lks. dist., mkd. T29S R7W S17 BT.
- A Fir 22" dia., bears S.71°E., 15 lks. dist., mkd. T29S R7W S20 BT.
- A Fir 7" dia., bears S.76°W., 67 lks. dist., mkd. T29S R7W S19 BT.
- A Maple 16" dia., bears N.14°W., 76 lks. dist., mkd. T29S R7W S18 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - May/June 1962 - C.S. File 49/139-77

-----  
Found - Orig. 24" now (?) R.Fir S.16°W., 9.2 ft. shows good scar. We do not open.

16" now 20" Maple N.14°W., 50.2 ft. shows scar.

Other 1924 BTs now snags.

New BTs -16" R.Fir bears S.34°E., 8.3 ft. scribed S20 T29S R7W CS BT.

7" W.Fir bears N.52°E., 46.7 ft. scribed S17 CS BT.

End of wire fence to East, S.70°E., 10.0 ft.

PRIMARY CORNER DESCRIPTION Sec Cor for 17, 18, 19 and 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - Karen Cheney; P.L. Earle - Jan. 10, 1977 - C.S. File 59/29-3

-----  
Found - 1924 GLO brass cap on a 2" I.P. approx. 7" above ground.  
An orig. 40" now 50" Fir, rotted stump, bears N.51°E., 9 ft. to center (Rec. 7.92 ft.) no visible scribing.  
An orig. 14" Fir now an 18" windfall, bears S.42½°E., 7.92 ft. no visible scribing.  
An orig. 24" Fir now 33" bears S.16°W., 9.24 ft. Alive and well healed with healed over blaze.  
An orig. 30" Fir now a stump, bears N.47°W., 7.26 ft. I do not open.  
1924 BT, a 14" Cedar, now a 15" dead windfall, bears N.24½°E., 55.4 ft. Faint scribing visible.  
A 22" Fir now a 26" down Fir, bears S.69°E., (Rec. S.71°E.) 9.4 ft. Broken off at root crown. Faint visible scribing "R7W". 1924 BT.  
A 16" Maple, now an 18" down Maple, bears N.14°W., 50.16 ft. Tipped out and well rotted. Healed over blaze. 1924 BT.  
The SW BT in the 1924 resurvey is gone.  
A 7" W.Fir now 13" bears N.52°E., 46.7 ft. Alive and well with well healed blaze. 1962 BT.  
A 16" R.Fir, now dead and down, bears S.34°E., 8.3 ft. No scribing visible. Healed blaze.  
New BTs -A 17" W.Fir bears S.68°E., 82.8 ft. Double blazed and scribed T29S R7W S20 CS BT.  
A 18" D.Fir bears N.64°W., 48.9 ft. Doubled blazed and scribed T29S R7W S18 CS BT.  
Fence line as recorded by Byron still in recorded place.

BLM resurvey by Daniel Weller and Dale Bedell under Group #1447, Surveyed June 1988/Feb. 1989 (DCS0 records Vol. 48 Page(s) 18536-37)

-----  
The cor., monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, with 1924 brass cap. from which the remains of the original bearing trees:  
A rotted Fir stump 40" dia., bears N.51°E., 12 lks. dist., with rotted face.  
A root hole bears S.42½°E., 12 lks. dist.  
A Fir 35" dia., bears S.16°W., 14 lks. dist., with healed blaze.  
A rotted Fir stump 26" dia., bears N.47°W., 11 lks. dist. with rotted face.  
(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a bearing tree mkd. by Byron, in 1962:  
A Fir 17" dia., bears N.50 3/4°E., 71 lks. dist., with  
healed blaze.  
and a bearing tree mkd. by Langlitz in 1977:  
A Fir 21" dia., bears N.65°W., 75 lks. dist., with healed  
blaze.  
and a new bearing tree:  
A Fir 11" dia., bears S.48½°E., 68 lks. dist., mkd. T29S  
R7W S20 BT.

Fd ok by BLM dependent resurvey by Bryan S. Seibold,  
Cadastral Surveyor, and Robert Browning, Surveying  
Technician, under Group #1745, surveyed Aug. 1994 thru  
April. 1995 - (DCSO records Vol. 52 Page(s) 20070-1)