

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Gary Langlitz; S. Flause; P. Earle - June 14, 1977 - C.S. File 59/34-36 and RM 3-8

Corner location determined by intersection of lines connecting opposite ¼ corners of Sec. 17.

Set 1" x 30" I.P. 26" in the ground on steep and brushy NW slope with brass cap attached marked:

Douglas County Surveyor

T 29 S R 7 W

C 1/4+S 17

1977

BTs - A 15" D.Fir scribed C 1/4 S17 CS BT" on a double blaze, bears N.31°E., 45.8 ft.

A 22" D.Fir scribed C ¼ S17 CS BT" on a single blaze, bears S.54°E., 23.8 ft.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1745, surveyed Aug. 1994 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20079-80)

The center ¼ sec. cor. of sec. 17, established by Langlitz, in 1977, and is accepted as the corner; monumented with an iron post, 1" diam., firmly set, projecting 4" above ground, with brass cap mkd.

DOUGLAS COUNTY SURVEYOR

T29S R7W

C1/4 + S 17

1977

from which the remains of bearing trees mkd. by Langlitz

A sawed fir stump, 15" diam., bears N.12°E., 69 lks., with scribe marks ¼ S17 CS BT visible on partially healed double blaze.

A fir, 27" diam., bears S.56½°E., 36 lks., with healed double blazes.

and a new bearing tree

A fir, 9" diam., bears S.51¼°W., 84 lks., mkd. C¼ S17 BT. The corner is located 3 lks. N. of a barbed wire fence extending E.-W.