

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 260360

PRIMARY CORNER DESCRIPTION NE 1/16 Cor. Sec. 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary Langlitz; L.E. Monrean;  
P. Earle; S. Flause - Oct. 17, 1977 - C.S. 59/40-44 & RM 3-8  
-----

Corner position determined by survey.  
Set 3" brass cap with 4" shank in bedrock 1" below rock  
surface at corner. Cap is marked:

Douglas Co. Surveyor Office  
T 29 S R 7 W  
NE 1/16 + S20 1977

Mound stone approx. 3 ft. at base and approx. 10" high around  
cap. Top of stone mound approx. flush with top of ground.

BTs - A 6" W.Oak bears N.40°E., 25.0 ft. scribed "NE 1/16 S20  
CS BT" on a double blaze.

An 18" P.Pine bears S.74°E., 29.2 ft. scribed "NE 1/16  
S20 CS BT" on a double blaze.

N.37°W., 86 ft. to a fence corner. Fence runs West and  
random South. Corner lies on a South slope approx. 80 ft.  
South of a northerly end of a natural clearing.