

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6535)

-----  
Set a post cor. of secs. 20, 21, 28 and 29, from which  
A B.Oak 9" dia., bears S.20°E., 81 lks. dist.  
A B.Oak 16" dia., bears N.21°E., 19 lks. dist.  
A W.Oak 18" dia., bears N.24°W., 80 lks. dist.  
A B.Oak 8" dia., bears S.64°W., 62 lks. dist.

Douglas Co. Surveyors Office - Ben B. Irving and James Bryon, Ray Irving - Work done for County Engineer for Rd. #38 - Feb. 1954 - C.S. File 46/36

-----  
Location identified from:  
Snag, 3 ft. high, 9" B.Oak S.20°E., 81 lks., visible reverse 8 BT.  
Snag, 12 ft. high, 16" B.Oak now 24", N.21°E., 19 lks. bottom blaze has been chopped out and is rotten.  
18" W.Oak now 24", dead, N.24°W., 80 lks. Blaze chopped out and tree rotten.  
8" B.Oak S.64°W., 62 lks., gone, pieces of oak roots visible.  
Set a 1" x 36" Iron pipe with brass cap stamped: County Surveyors Office, T29S R7W S20 S21 S28 S29, 1954, from which  
A Fir 15" dia., N.28°E., 18.8 ft. blazed and scribed T29S R7W S21 CS BT.  
A Fir 10" dia., N.19½°W., 28.9 ft. blazed and scribed T29S R7W S20 CS BT.  
A Fir 7" dia., S.50½°W., 15 ft. blazed and scribed T29S R7W S29 CS BT.  
A Fir (?)" in dia., S.33°E., 38.4 ft. blazed and scribed T29S R7W S28 CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - May 1962 - C.S. File 49/139-64

-----  
Found - Brass cap at cor. and one BT standing, a 7" R.Fir S.50½°W., 15.0 ft.  
New BTs -10" R.Fir N.4°W., 56.6 ft. scribed S20 T29SR7W CS BT.  
12" R.Fir N.56½°E., 88.0 ft. scribed S21 T29SR7W CSBT  
No trees near to SE.

BLM resurvey by John M. Jelley, under Group #346, Surveyed, Aug./Oct. 1966 - (DCSO records Vol. 34 Page(s) 14295-96)

-----  
The Sec. cor., perpetuated and recorded by Byron in 1954, monumented with an I.P. 1" dia., firmly set, extending 4" above the ground, with brass cap mkd (Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

COUNTY SURVEYORS OFFICE

T 29 S R 7 W

S 20 | S 21

S 29 | S 28

1954

from which the remaining original bearing trees

The rotted remains of an oak stump, size indeterminate, bears N.21°E., 19 lks. dist.

A rotted oak stump 15" dia., bears S.20°E., 81 lks. dist., with scribe marks S BT visible in negative on overgrowth.

A down oak 24" dia., bears N.24°W., 80 lks. dist., with rotted blaze, no marks remaining.

and bearing trees marked by Byron in 1962

A Fir 16" dia., bears N.56½°E., 133 lks. dist., with scribe marks T29S R7W S21 CS BT visible on partly healed double blaze.

A Fir 13" dia., bears N.4°W., 86 lks. with healed blaze.

and a bearing tree of which I have no record:

A Fir snag 8" dia., bears S.50½°W., 22½ lks. dist., with healed double blaze.

and new bearing trees:

A Fir 10" dia, bears S.31½°E., 160 lks. dist., mkd. T29S R7W S28 BT.

A Fir 7" dia., bears S.50½°W., 140 lks. dist., mkd. T29S R7W S29 BT.

Add BLM 1966 to brass cap.

Fd. OK - Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Jan. 1998 - C.S. File 64/79-9

FD. OK by M. Heimbürger - 1/2007 - M146-52  
Lat: 43°01'46.9163" Long: -123°32'41.1745"