

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22 and 27 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6524)

Set a post, cor. of secs. 22, 23, 26 and 27, from which
A Red Fir 18" dia., bears S.13°E., 20 lks.
A Cedar 24" dia., bears S.50°W., 27 lks.
A Red Fir 20" dia., bears N.45°E., 14 lks.
A Red Fir 12" dia., bears N.43°W., 7 lks.

GL0 survey by Mensch under Instructions dated April 18, 1924 (DCSO records Vol. 14 Page(s) 5970)

Intersect the point for Ford's cor. of secs. 22, 23, 26 and 27, located by measurement from the original bearing trees. At the exact cor. point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 22 and 27, on the W. bdy. of sec. 23, with brass cap marked:

T29S	
S22	
S27	S23
R7W	
	1924

from which (the original bearing trees)
A Cedar snag bears S.50°W., 21 lks. dist., marks plain.
A Fir, uprooted, bears S.13°E., 20 lks. dist., blazes are plain on the log.
A Fir stump hole, bears N.45°E., 14 lks. dist.
New Bearing trees:
A Fir 22" dia., bears S.70°W., 66 lks. dist., marked T29S R7W S27 BT.
A Fir 12" dia., bears N.81°W., 31 lks. dist., marked T29S R7W S22 BT.

Douglas Co. Surveyors Office - Ben B. Irving - Wit: N.E. Richardson - July 30, 1938 - (No record source found, see "old" corner book, Pg. 175)

Corners as recorded in the Govt. field notes in place except that the tree to the NW has been destroyed.
Blazed and scribed:
A Fir 8" dia., which bears N.29°W., 93 lks., T29S R7W S27 CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; J. Halterman - Nov. 27, 1963 - C.S. File 49/139-109

Found - 1924 GL0 brass cap at corner.
(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. cor. for 22 and 27 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

30" Red Fir S.70°W., 43.6 ft. shows good scar. Rotted stump of NW BT. New BT - 6" Red Fir bears N.54°W., 11.4 ft. scribed S22 CSBT.
Brass cap and 5 BTs found OK, BLM survey by Jelley and Rogers, 1981 (DCSO records Vol. 43 Page(s) 16665)
Found OK by W. Rogers, Oct. 2001 - M139-3