

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Roy T. Campbell, under Contract #789 dated Aug. 21, 1909, (DCSO records Vol. 16 Page(s) 6565)

Set a basalt stone 15 x 12 x 6 ins., 10" in the ground, for 1/4 sec. corner, marked 1/4 on N. face, from which
A Madrona 30" dia., bears N.46°E., 139 lks. dist., mkd. 1/4 S23 BT.
A Fir 30" dia., bears S.64°45'W., 62 lks. dist., marked 1/4 S26 BT.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - May 1962 (Added 5/10/2021) - C.S. File 51/163-2

Found - 15" by 12" by 6" stone.
30" Madrone N.46°E., 139 lks. (Good condition, rescribed 1/4 S BT)
30" Fir S.64 3/4°W., 62 lks. (Stump)
Set - 1 1/4" by 24" iron pipe
Scribed- 36" Cedar S.25°E., 17.0 ft.

BLM resurvey by Jolley/Rogers, under Group #1044 - Surveyed, Jan/April 1981 (DCSO records Vol.43 Page(s) 16667)

The 1/4 sec. cor. monumented with the original unmarked basalt stone, 15 x 12 x 6", firmly set, projecting 6" above ground, alongside of which is an iron pipe, 1 1/2" dia., firmly set, projecting 6" above ground, from which the remains of the original bearing trees:

A Madrone 36" dia., bears N.46°E., 139 lks. dist., with scribe marks 1/4 S BT visible on open blaze.

A sawed Fir stump 27" dia., bears S.64 3/4°W., 62 lks. dist., with healed blaze.

and the remains of a bearing tree of which I have no record

A Cedar snag, 36" dia., bears S.25°E., 26 1/2 lks. dist., with scribe marks 1/4 S BT visible on open blaze.

At the cor. point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd. T 29 S R 7 W

1/4 $\frac{S\ 23}{S\ 26}$

from which new bearing trees

A Fir 11" dia., bears N.19°E., 12 1/2 lks. dist., mkd. 1/4 S23 BT.

A Fir 9" dia., bears S.49 1/2°E., 6 lks. dist., mkd. 1/4 S26 BT.

Deposit corner stone and reset iron pipe alongside iron post.