

PRIMARY CORNER DESCRIPTION Wit. Point in Sec. 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6520)

Set a post at proper distance, cor. of secs. 1, 2, 35 and 36, from which

- A Red Fir 12" dia., bears S.55°W., 10 lks. dist.
- A Red Fir 4" dia., bears N.25°W., 12 lks. dist.
- A Red Fir 10" dia., bears S.15°E., 50 lks. dist.
- A Red Fir 4" dia., bears N.50°E., 35 lks. dist.

GL0 survey by Mensch under Instructions dated April 18, 1924 (DCSO records Vol. 14 Page(s) 6046)

Intersect the point for Ford's cor. of secs. 1, 2, 35, and 36, located by measurement from the original bearing trees, which are as recorded.

- A Fir 24" dia., bears S.15°E., 50 lks. blazes are plain.
- A Fir 26" dia., bears S.55°W., 10 lks. blazes are plain.
- A Fir 7" dia., bears N.25°W., 12 lks. marks plain on the bark.
- A Fir bears N.50°E., 35 lks. dist., has rotted away, but stump hole indicates position.

At the exact cor. point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for witness point, with brass cap marked:

WP
1924

from which new bearing trees:

- A Fir 12" dia., bears N.51°E., 45 lks. dist., mkd. WP BT.
- A Fir 30" dia., bears N.10°W., 50 lks. mkd. WP BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - June 1962 - C.S. File 49/139-88

Found - Orig., now 30" Fir S.55°W., 6.6 ft. shows old scar, also bark scribing "WP". (1924)

Both 1924 BTs. NW BT, down.
Open NE BT and find good scribing "BT".

We do not find brass cap at corner. There has been no logging in this area nor other activity to remove or destroy brass cap.

Set Brass cap at cor. and mkd: County Surveyors Office, 1962

W P S35 T29S R7W

Corner is on East slope and about 100 ft. West of draw.