

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854, (DCSO records Vol. 15 Page(s) 6525)

Set a post, cor. of secs. 13, 14, 23 and 24, from which
A Laurel 24" dia., bears N.70°W., 110 lks. dist.
A Cedar 15" dia., bears S.37°W., 105 lks. dist.
A B.Oak 7" dia., bears S.33°E., 40 lks. dist.
A B.Oak 8" dia., bears N.76°E., 55 lks. dist.

GLO survey by Roy Campbell, under Group #789 dated Aug. 21 1909, (DCSO records Vol. 15 Page(s) 6562-63)

Intersect E. and W. line at the corner of secs. 13, 14, 23 and 24, which is a post, 4" square, 12" above ground, badly decayed. The bearing trees are dead.
I re-establish the corner at the same point, as follows:
Set a Cedar post, 4" square, 3 ft. long, 24" in the ground, for cor. of secs. 13, 14, 23 and 24, marked T29S S13 on NE., R7W S24 on SE., S23 on SW. and S14 on NW., with 3 notches on S. and 1 notch on E. edge, from which
A Fir 10" dia., bears N.76°E., 41 lks. dist., mkd. T29S R7W S13 BT.
A Fir 30" dia., bears S.67°30'E., 46 lks. dist. mkd. T29S R7W S24 BT.
A Fir 30" dia., bears S.73°W., 28 lks. dist., mkd. T29S R7W S23 BT.
A Fir 18" dia., bears N.13°W., 52 lks. dist., mkd. T29S R7W S14 BT.

J.W. Cole - Nov. 23, 1923 - Vol. 3 Pg. 172 and C.S. File 6/33

I found stake nearly decayed and erected mound of rock 24" dia., 18" high, from which original trees:
A Fir 24" dia., S.66°E., 29.6 ft.
A Fir 24" dia., N.13°W., 33.0 ft.
A Fir 28" dia., S.74°W., 17.1 ft.

GLO survey by Mensch under Instructions dated April 18, 1924 (DCSO records Vol. 14 Page(s) 5974)

Intersect the Campbell cor. of secs. 13, 14, 23 and 24, which is a Cedar post, 4" sq., 12" above ground, firmly set, marked T29S S13 on NE., R7W S24 on SE., S23 on SW., and S14 on NW. face, with 3 notches on S. and 1 notch on E. edge; from which (the original bearing trees)
A Fir 32" dia., bears S.67½°E., 46 lks. dist., mkd. T29S R7W S24 BT.
(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A sawed, decayed fir stump, 30" dia., bears S.73°W., 18.5 ft., with scribe marks T29S and other fragmentary scribe marks visible on a chopped open blaze.
A fir, 56" dia., bears N.13°W., 34.3 ft., with a healed blaze.
and the remains of bearing trees mkd. by Thielsen in 1957
A fir, 37" dia., bears N.73°E., 110.2 ft., with a healed blaze.
A sawed, decayed fir stump, 27" dia., bears S.45°E., 81.8 ft., with scribe marks T29S R7W visible on an open blaze.
A fir, 32" dia., bears S.14°W., 91.1 ft., with a healed blaze.
and a new bearing tree
A cedar, 11" dia., bears S.10¼°E., 28.3 ft., mkd. T29S R7W S24 BT.
Corner is located on a NE. slope.

David Edwards - For: Seneca Jones Tmbr Co. - 5/2020 - M177-4

Found as per 2011 BLM resurvey **with the exception** that the 11" cedar S.10¼°E., 28.3' is down.
A 6 ft steel post is set 2 ft South.

3