

PRIMARY CORNER DESCRIPTION Sec. Cor. 1 & 2; 35 & 36, T28-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Page 5747)

Set a post at proper distance, cor. of secs. 1, 2, 35 and 36, from which

- A B.Oak 10" dia., bears S.30°W., 88 lks. dist.
- A B.Oak 8" dia., bears S.80°E., 70 lks. dist.
- A B.Oak 7" dia., bears N.57°W., 15 lks. dist.
- A B.Oak 9" dia., bears N.23°E., 21 lks. dist.

J.W. Cole, Co. Surveyor - For: Thomas Parkinson (crew, Ed Walker; Chas. Voytilla) Oct. 1923 - C.S. File 6/33; Vol. 3 Page 171

Renewed corner from facings of original BTs whose bearings all check closely but distances do not.

Set Fir stake 3 x 3 x 36 for corner, from which new trees:

- A Fir 14", N.72°30'E., 17.0 ft.
- A Fir 10", S.3°30'W., 12.0 ft.
- A Fir 10", S.65°W., 18.0 ft.
- A Fir 12", N.25°W., 16.2 ft.

Doug. County Surveyors Office - James Byron, Deputy - V.R. Tracy; J. Heritage; V. Perron - March 1969 - C.S. File 54/83; M 33-57

-
- Found - 14" now 16" Fir N.72½°E., 17.0 ft. (face) bark scribed "S36 CS BT". We rescribe "T28S R7W S36 CS BT".
- 10" now 13" Fir stump S.3½°W., 12.0 ft. (face) bark scribed "S1 CSBT".
- 10" now 13" Fir stump S.65°W., 18.0 ft. (face). No scribe found, cut off low.
- 12" now 16" Fir N.25°W., 16.2 ft. (face) bark scribed "S35 CS BT". We rescribe "T28S R7W S35 CS BT".

Set Brass cap at cor. mkd: County Surveyors Office, 1969

- | | | |
|------|------|-----|
| T28S | S 35 | S36 |
| R7W | S 2 | S 1 |
- New BTs -12" D.Fir S.55°E., 21.9 ft. (center) mkd. T29S R7W S1 CS BT.
- 13" D.Fir S.71°W., 77.1 ft. (center) mkd. T29S R7W S2 CS BT.

The only remains of orig. BTs were down & out of place, no scribe. Fence corner bears N.15°E., 5.5 ft., fence E & N.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. 1 & 2; 35 & 36, T28-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Bryan S. Seibold, & Robert J. Chappel, Cadastral Surveyor, under Group #1585, surveyed May 1991/May 1994 - (DCSO records Vol. 52 Page(s) 19991-2)

The cor. of secs. 1, 2, 35, & 36, perpetuated by Cole, Deputy County Surveyor, in 1923, from original evidence no longer in existence, recorded in the Douglas County Surveyors Office, further perpetuated by Byron, Douglas County Surveyor, in 1969, recorded in the Douglas County Surveyor Office, monumented with an iron post, 1½" diam., firmly set, projecting 14" above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

		T28S	
R	S	35	S 36
7	S	2	S 1
W		T29S	
		1969	

from which the remains of bearing trees mkd. by Cole

- A fir, 19" diam., bears N.71°E., 24½ lks., with healed blaze.
- A rotted, sawed, fir stump, 14" diam., bears S.7°W., 19 lks., no marks visible.
- A rotted, sawed, fir stump, 12" diam., bears S.64 3/4°W., 28½ lks., no marks visible.
- A fir, 19" diam., bears N.27½°W., 26½ lks., with healed blaze.

and the remains of bearing trees mkd. by Byron

- A dead fir, 11" diam., bears S.55¼°E., 33 lks., with healed blaze.
- A fir, 16" diam., bears S.70¼°W., 115 lks., with healed blaze.

and a new bearing tree

- A madrone, 10" diam., bears S.39¼°E., 23 lks., mkd. T29S R7W S1 BT.

The corner is located S.16°W., 0.08 chs. from a fence corner, with 4 strand barbed wire fence extending N. and woven wire fence extending E.

James Klein & Michael Erickson - For: Pacific Connector Gas Pipeline Project/Williams - Sept. 2014 - M166-23 A-C

Found - 2½" brass cap stamped COUNTY SURVEYORS OFFICE 1969
 20" Fir with healed face and tag dated 6/92;
 N.71°E., 16.5'
 14" Madrone and tag dated 6/92; S.39¼°E., 15.2'
 8" dead fir snag with healed face and tag dated
 3/26/69; S.55°E., 21.91'. continued next pg

