

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 24 and 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Roy T. Campbell, under Group #789 dated Aug. 21, 1909, (DCSO records Vol. 15 Page(s) 6563-64)

-----  
Set a Fir post, 4" square, 3 ft. long 24" in the ground, marked ¼ S24 on N., and 25 on S. face, from which  
A Fir 12" dia., bears N.59°30'E., 47 lks. dist. mkd. ¼ S24 BT.  
A Fir 14" dia., bears S.67°45'W., 6 lks. dist., marked ¼ S25 BT.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - N.E. Richardson; Frank Royer; Robinette; Bill Weightman - May 1934 - M 1-27 and C.S. File 37/171

-----  
Original BTs as described in Govt. field notes.  
Set Yew wood post, 4" x 4" x 36" -- ¼ S. 24-25 C.S.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell Dale McFarland - April/May 1962 - C.S. File 49/139-58

-----  
Found - Orig. 14" now 20" Fir snag S.67 ¾°W., 4.0 ft., shows good scribing on old face "2"  
Orig. NE BT, not found.  
Set Brass cap at cor. mkd: County Surveyors ¼ S24 T29S R7W Office 1962 S25  
New BTs -16" W.Fir bears S.33°W., 33.6 ft. scribed ¼ S25 CS BT.  
10" R.Fir bears N.45°W., 76.5 ft. scribed ¼ S24 CSBT  
Corner is at NE corner of a bench.

Howard Johnstone - For: Roseburg Resources - Aug. 1989 M 101-60

-----  
Found - 1962 County brass cap and iron pipe.  
12" Fir N.45°W., 76.5 ft., healed.  
16" Fir S.33°W., 33.6 ft., rotten stump.  
New BT - 10" Fir S.13°W ., 38.0 ft. scribed "¼ S BT".

David Edwards - For: Roseburg Resources - 6/2016 - M172-16

-----  
Found - Brass cap.  
18" dia., fir bears S.13°W., 38.0 ft. }healed blaze  
26" dia., fir bears N.45°W., 76.5 ft. }  
A six ft steel post is set 2 ft. east.