

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 13 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854) (DCSO records Vol. 15 Page(s) 6525)

(Common Corner)

Set ¼ sec. post, at average distance, from which

A Red Fir 24" dia., bears S.35°W., 18 lks.

A Laurel 12" dia., bears N.10°E., 35 lks.

GLO survey by Roy T. Campbell, under Contract #789 dated Aug. 21, 1909 (DCSO records Vol. 16 Page(s) 6566-67)

Set temporary ¼ sec. corner. After diligent search I am unable to find any trace of old ¼ sec. cor.

I proceed to re-establish the ¼ sec. corner at a point equidistant from the two sec. cors., as follows:

Set a Cedar post, 3" square, 3 ft. long, 24" in the ground, for ¼ sec. corner, marked ¼ S13 on N., and 24 on S., from which

A Fir 18" dia., bears N.14°E., 70 lks. dist. mkd. ¼ S13 BT

A Madrona 24" dia., bears S.24°W., 82 lks. mkd. ¼ S24 BT.

GLO survey by Mensch under Instructions dated April 18, 1924 (DCSO records Vol. 14 Page(s) 5974)

Found Campbell's Post and 2 bearing trees.

GLO resurvey by Hans Theilsen, under Group #346, Surveyed, 1957 (DCSO records Vol. 28 Page(s) 12147)

The 1/4 sec. cor. of sec. 13 only, determined at record bearing and distance from the remaining bearing tree marked by Campbell in 1910 as follows:

A Fir snag 14" dia., bears N.14°E., 70 lks. dist., marked ¼ S13 BT on partly healed blaze.

At the cor. point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

T29S R7W

¼ S 13

1957

from which new bearing trees

A Cedar 5" dia. bears N.19°E., 149 lks. dist., marked ¼ S13 BT.

A Cedar 7" dia., bears N.14°W., 118 lks. dist., marked ¼ S13 BT.

continued next page

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 13 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Howard Johnstone - For: Roseburg Resources - Aug. 30, 1989
M 101-60

Found - 1957 GLO brass cap and iron pipe.
12" Cedar N.19°E., 98.3 ft.
New BTs -7" Fir N.15°E., 16.7 ft. scribed ¼ S13 BT.
10" Fir N.48°E., 30.3 ft. scribed ¼ S13 BT.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral
Surveyor, under Group No. 2270, Surveyed May/Aug. 2009 -
(DCSO records Vol. 57 Page(s) 22744)

The ¼ sec. cor. of sec. 13 only, perpetuated by Johnstone, in
1989, monumented with an iron post, 1" dia., firmly set,
projecting 13" above ground, with brass cap (properly) mkd.
from which the remains of BTs mkd. by Thielsen in 1957

A cedar, 20" dia., bears N.19°E., 98.3 ft., with a healed
blaze.

A decayed cedar stump, size indeterminate, bears N.14°W.,
77.9 ft., with scribe marks S13 BT and other
fragmentary scribe marks visible on decayed root crown.
and bearing trees mkd. by Johnstone

A fir, 14" dia., bears N.11°E., 16.8 ft., with a healed
blaze.

A fir, 15" dia., bears N.45½°E., 30.2 ft., with a healed
blaze.

Corner is located at the terminus of a barbed and woven wire
fence extending S.88°E.

Fd. As per 2011 BLM resurvey 5/2020 - D. Edwards - M177-4