

PRIMARY CORNER DESCRIPTION SE Tsp. Cor. - Sec 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6456 & 6457)

Set a post, cor. of secs. 1, 6, 31 and 36, from which
A W. Oak, 8" diam., bears S.53°W., 53 lks.
A W. Oak, 7" diam., bears S.63°E., 19 lks.
A W. Oak, 7" diam., bears N.27°W., 30 lks.
A W. Oak, 30" diam., bears N.35°E., 35 lks.

Re-Establishment of corners by Fred Mensch, US Dep. Surveyor - under date of Dec. 4, 1905 (DCSO Vol. 15 Pg. 6503 & 6504)

I find corner partially obliterated. The oaks described as bearing trees in secs. 1 and 31 are standing, with marks yet distinguishable. The other bearing trees have disappeared. I destroy the old marks and re-establish the corner in its original position as follows:

Set a diorite stone 15x12x10", 10" in the ground for cor mkd. with 6 notches on each edge, from which:
A W. Oak, 24" diam., bears N.73°E., 22 lks., mkd. T29S R6W S31 BT.
A W. Oak, 18" diam., bears S.20°E., 50 lks., mkd. T30S R6W S6 BT.
A Yellow Pine, 36" diam., bears S.19°W., 46 lks., mkd. T30W R7W S1 BT.
A Cedar, 12" diam., bears N.49°W., 150 lks., mkd T29S R7W S36 BT.

John H. Markham Jr. - for Stomar Lumber Co. - Apr/Sep 1956 -C. S. 41/191-1

Point for corner determined by OBT's:
A 24" W.O., bears N.73°E., 14.5 ft., I rescribe S 31 BT.
A 20" W. O., bears S.20°E., 33 ft., I rescribe S 6 BT.
A 44" Y. Pine windfall, bears S.19°W., 30.4 ft., OBT.
At corner point Set 2" x 36" solid steel bolt, from which:
A 21" W.O., bears N.49°W., 177 ft., mkd. S36 T29S R7W., BT.
A 22" Laurel, bears N.4°E., 55 ft. mkd. S31, T29S R6W, BT.
A 14" W.O., bears S.33°E., 30.5 ft., mkd. S6 T30S R6W, BT.
An old fence runs N - S.

James W. Byron, Dep. Co. Surveyor - Crew: Dale McFarland and John Powell - Apr 1962 - C.S. 49/139-34 & C.S. 52/25-12

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SE Tsp. Cor - Sec. 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - All bearing trees as recorded by Markham, 1956. We do not find Bolt set at corner.

Set Brass cap mkd: County Surveyors S36|S31 T29S
Office, 1962 R7W S1|S 6 R6W T30S

Note - We find stone N.20°W., 1.5 ft., from corner that may have been set for corner.

BLM Resurvey - Lynn Roseberry, Cadastral Surveyor - Group #669 - Apr 1968 (DCSO records Vol. 35 Pg. 14451-52)

The cor. of Tps. 29 & 30 S., Rs. 6 & 7, remonumented by Fred Mensch in 1905 with a diorite stone, 15x12x10" firmly set, 10" in the ground, mkd with 6 notches on N., E., S., and W. edge; from which bearing trees mkd by Mensch:

A W. Oak, 27" diam., bears N.81½°E., 22 lks., with partially healed original blaze. This tree was rescribed S31 BT by J. Markham in 1956, (Record, N.73°E.).

A W. Oak, 21" diam., bears S.20½°E., 50 lks., with scribe mark B visible on partially healed original blaze. This tree was rescribed S6 BT by J. Markham, (Record, S.20°E.).

A root hole, bears S.19°W., 46 lks., with a down pine alongside, 36" diam., no marks visible.

A root hole, bears N.50½°W., 150 lks., (Record N.49°W). and bearing trees by J. Markham

A madrone, 33" diam., bears N.3°E., 80½ lks., with scribe mks S31 T29S R6W BT visible on partially healed blaze.

A W. Oak, 16" diam., bears S.31¼°E., 48½ lks., with scribe mks S6 T30 R 6 BT visible on partially healed blaze.

A W. Oak, 25" diam., bears N.50°W., 267 lks., with scribe marks 3 29S 7 B visible on partially healed blaze.

The corner point

Set an iron post 28" long, 2½" diam., 24" in the ground with brass cap mkd.

T 29 S
R7W | R6W
S36 | S31
S 1 | S 6
T 30 S
1968

from which a new bearing tree

A fir, 5" dia., S.49°W., 18½ lks., mkd. T30S R7W S1 BT. Deposit the corner stone alongside the iron post.

From this point, an iron post set by the County Surveyor in 1962, 1" dia., protruding 12" above the ground, firmly set, with brass cap, bears S.23½°E., 0.025 chs. dist.

(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION SE Tsp. Cor. - Sec. 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM 1968 Corner Fd. OK, Wayne Rogers, BLM survey, 1980, (DCSO records, Vol. 45 Page 17256) and

Fd. OK, by Jolley, 1980 Cadastral survey, 1980-1982 (DCSO records, Vol. 43 Pages 16787-88)

Gregory Quibell, Dep. Doug. Co. Surveyor - John Powell & Randy Smith - Jan 28, 1983 - C.S. 62/7-9

Found - 1962 DCSO brass cap properly marked and firmly set.
1968 BLM brass cap per resurvey properly marked and firmly set with what appears to be the original corner stone buried alongside. DCSO brass cap bears S.23½°E., 1.65 ft. from BLM cap.
Found all accessories as described in 1968 resurvey and Lloyd Smith survey. (M 93-45)
My measurement to the two remaining original BTs from each of the brass caps plus faint notches on all four edges of the found stone cause me to accept the position of the BLM brass cap as the proper corner location. I then cut the DCSO brass cap off and drive a yellow nylon cap inside the remaining 1" I.P. Cap marked "Doug. Co. Surveyor".

DCSO-GIS Corner visitation - 8/5/2004 - Typed: 2/1/2011 - C.S. File 67/33-1

Monument - GLO/BLM 2.5" BC/IP
Comment - ok