

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 140160

PRIMARY CORNER DESCRIPTION Center N. 1/16 Cor. for Sec. 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #584 - Surveyed July 1965 - (DCSO records Vol. 33 Page(s) 13888)

Point for the center 1/16 sec. cor. of sec. 31.
Set an iron post 28" long, 2½" dia., 23" in the ground, with brass cap mkd. C
N 1/16 S 31
C
1965

from which
An Oak 11" dia., bears N.30°E., 39 lks. dist. mkd. CN 1/16 S31 BT.
A Fir 14" dia., bears S.75 3/4°W., 42½ lks. dist. mkd. CN 1/16 S31 BT.

Douglas Co. Surveyors Office - R.B. Kimberling; M.W. Cline - oct. 10, 1977 - C.S. File 59/40-37

Found - 1965 BLM brass cap, properly mkd., 6" above ground. Pipe was not bent but 30° from vertical and brass cap fastening bolt was broken.
An 11" W.Oak bears N.30°E., 25.7 ft. with a rotted out blaze.
A 14" Fir snag, 35 ft. tall bears S.75 3/4°W., 28.0 ft. with scribing "CN 1/16 S31 BT" in single unhealed blaze.
Secured brass cap on iron pipe and reset from bearing trees 5" above ground and stamped "Reset 1977" on brass cap.
New BT - 8" Cedar bears S.6°E., 22.9 ft. double blazed and scribed "CN 1/16 S31 CS BT".

Fd. and used in resurvey by BLM resurvey by Wayne L. Rogers, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1583 - Surveyed April/June 1991 - (DCSO records Vol. 49 Page(s) 18673-74)