

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6604)

Set ¼ sec. post, from which
 An Ash 12" dia., bears S.85°E., 453 lks. dist.
 An Oak 20" dia., bears N.0°30'W., 1780 lks. dist.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit: W.S. Crear; C. McCann; Wm. Porter - Dec. 1927 - M 1-63; Vol. 3 Page 281; C.S. File 7/38

Found 12" Ash in position with proper blazes but figures burned and rotted off. Also old Oak which appeared to have formerly been the original BT, found mark 1" long which seemed to be a scribe mark. Oak down and stump burned off. Bank washed out where it formerly stood. Bearing and distances check exactly.
Set sandstone for corner 6" x 8" x 20", chiseled ¼ and X., 10" under ground.
New BTs- A 14" Fir S.32°25'E., 470 lks. scribed ¼ S17 CSBT.
 A 40" Fir N.56°24'W., 1022 lks. scribed ¼ S18 CSBT

Douglas Co. Surveyors Office - James W. Byron, Deputy - Wit: Dale McFarland; John Powell - April 6, 1962 - For: Doug. Co. Health Dept. - C.S. File 52/114; RM 2-20

Set Brass cap 262.0 ft. East of corner mkd. "County Surveyors Office 262.0 ft. to ¼ S18 S17 T29S R8W", from which
 10" R.Fir bears N.2°E., 33.9 ft. scribed W.C. ¼ S17 CS BT.
 12" R.Fir bears S.71°E., 2.0 ft. scribed W.C. S17 CS BT.
Found sandstone rock 12" under with + on top. Set ¾" I. Rod at ¼ corner flush with top of rock.

BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15768)

The ¼ sec. cor., perpetuated by Irving in 1927, from original evidence no longer in existence, subsequently perpetuated by Byron in 1962, monumented with an iron rod, ¾" dia., with top 12" below surface of ground.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 52" in the ground, directly over iron rod, with top 24" below surface, with brass cap mkd: (Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 29 S R 8 W
 $\frac{1}{4}$
S 18 S 17
1973

No suitable trees available within limits.
Corner is located in large open field.

From this corner, a point established by Byron for a witness corner, bears N.89°00'E., 3.970 chs. dist., monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap mkd. in 1962, from which bearing trees mkd. by Byron

A Fir 12" dia., bears N.2°E., 51½ lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

A Fir snag 12" dia., bears S.69½°E., 3½ lks. dist., with scribe marks S17 CS visible on partially healed double blaze.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1776, surveyed Oct./Nov. 1995 - (DCSO records Vol. 52 Page(s) 19927-8)

¼ sec. cor. of secs. 17 & 18, monumented with an iron post, 2½" diam., firmly set 24" below ground, with brass cap mkd.

T29S R8W
 $\frac{1}{4}$
S 18 S 17
1973

from which the remains of a BT mkd. by Irving, in 1927

A sawed fir stump, 45" diam., bears N.56½°W., 1022 lks., with scribe marks ¼ C BT visible on the bark, stump is partially tipped up and out of the ground.

and a new bearing tree

A fir, 21" diam., bears N.65°E., 483 lks., mkd. ¼ S17 BT. The corner is located in a large grass field.

From this point, a reference monument established as a witness cor. to the ¼ sec. cor. of secs. 17 & 18 by Byron, in 1962, recorded RM2-20, bears N.88°46'54"E., 3.970 chs.; monumented with an iron post, 1¼" diam., firmly set, projecting 12" above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T29S R8W W.C. 262' WEST TO 1/4 S18 S17 1962, & an arrow pointing to the corner, from which the remains of bearing trees mkd. by Byron:

A fir snag, 10" diam., bears N.0 ¾°E., 51 lks., with fragmentary scribe marks visible on partially healed double blaze.

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, size indeterminate, bears S.76¼°E.,
3 lks., no marks visible.
The witness cor. is located W., 0.12 chs. of a drainage
ditch, 15 lks. wide, ditch bears N. and S.10°W.