

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6602)

-----  
Set ¼ sec. post, from which  
    An Oak 12" dia., bears N.48°W., 198 lks. dist.  
    An Oak 12" dia., bears S.6°W., 104 lks. dist.

Jesse W. Cole, County Surveyor - Wit: N.E. Richardson; Mr. Nicewood - April 23, 1923 - Vol. 3 Page 148

-----  
Set a steel mower pitman, from which  
    A Fir 18" dia., S.77°20'E., 74.3 ft.  
    A Sugar Pine 26" dia., N.62°40'E., 150.0 ft.  
No evidence of original corner to be found. This corner was set by proportionate measure.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 1965 - C.S. File 54/38-1

-----  
Found - 1" steel shaft and live BT as recorded by Cole.  
    18" now 27" Fir S.77°20'E., 74.3 ft., open and shows partial "S".  
    26" now 35" S.Pine N.62°40'E., 150.0 ft., now stump, no scribe visible.  
New BT - 6" D.Fir N.48°E., 14.3 ft. mkd. ¼ S20 CS BT.  
Corner is in E-W fence 22.0 ft. East of fence corner with fence going E-W and S.

Fd. OK, Dec. 1984 by E. Bloom - M 98-14  
Fd. OK, Aug. 1999 by C. Sweeden - 2001-0009

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2097, surveyed Sept. 2004 (DCSO rec. Vol. 55 pg(s) 21287-8)

-----  
The ¼ sec. cor. of secs. 20 & 29, reestablished by the Douglas County Surveyor's Office in 1923, at proportionate measurement, and perpetuated by the Douglas County Surveyor's Office in 1965. There is no remaining evidence of the original cor., therefore this point is accepted as the cor., monumented with a steel shaft, 1" dia. firmly set, projecting 2" above ground, from which the remains of bearing trees mkd. by the Douglas County Surveyor's Office in 1923  
    A decayed pine stump, size indeterminate, bears N.63°E., 149.7 ft., with no marks visible.  
    A fir, 33" dia., bears S.76¾°E., 75.1 ft., with a healed double blaze.                      continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

and a bearing tree mkd. by the Douglas County Surveyor's Office in 1965

A fir, 26" dia., bears N.48°E., 14.8 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 20" in the ground, over the existing steel shaft, with brass cap mkd.

T29S R8W

¼      S 20  
         S 29

2004

Corner is located at the intersection of fences extending East, South, and West.

Fd. BC by D. Edwards, 8/2011 - M162-80