

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6596)

Set post cor. secs. 20, 21, 28 and 29, from which
A Laurel 12" dia., bears N.85°W., 30 lks. dist.
A Laurel 10" dia., bears S.40°W., 66 lks. dist.
A Fir 6" dia., bears N.22°E., 50 lks. dist.
A Fir 6" dia., bears S.27°E., 48 lks. dist.

Jesse W. Cole, County Surveyor - Wit: N.E. Richardson; Mr. Nicewood - April 23, 1923 - Vol. 3 Pg. 148 (and "old" corner book, page 135)

Renewed this corner from the original Fir bearing trees. Also Cedar line tree, North 25 lks., the stump of which still existed.
I set a Cedar post 4" x 4" x 36", from which
Orig. Fir bearing scribe marks N.22°E., 50 lks.
Orig. Fir, did not open, S.27°E., 48 lks.
New BT, 26" Fir S.49°15'W., 41.0 ft.
New BT, 30" Chinquapin S.66°E., 47.0 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-33

Found BTs as recorded by Cole, 1923:
The SW. BT, now stump, shows good scribing.
NE. BT, shows good scar.
SE. BT, shows good bark scribing, now dead.
Orig. S.27°E. BT has log at base, impossible to read.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
S 20 | S 21
S 29 | S 28
1958
New BTs- 24" double Laurel N.80½°W., 29.6 ft. scribed S20 T29S
R8W CS BT.
18" R.Fir bears S.18°E., 14.8 ft. scribed S28 T29S
R8W CS BT.
20" R.Fir bears N.22°E., 34.3 ft. scribed S21 T29S
R8W CS BT.
14" Chinquapin S.69°W., 12.0 ft. scribed several years ago, partly covered.
Fence to North and to West, bears N.45°W., 3.0 ft.

Fd. brass cap, Dec. 1984 by E. Bloom - M 98-14 cont.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
- Nov. 10, 1997 - C.S. 64/78-26

-
- Mon. Fd.- 2½" dia. Brass cap on a 1½" O.D. iron pipe protrudes 14" above ground. 1958
 - Bt's Fd.- 6" now 24" dia. D.Fir, with a fully healed double blaze, bears N.20½°E., 34.3' (rec. N.22°E., 33' orig. and N.22°E., 34.3' 1958) OBT.
 - 6" now broken D.Fir snag no marks visible near record "S.27°E., 31.7'" OBT.
 - 24" now double trunked madrone main trunk is 25" dia. northerly trunk is cut and blaze is rotted we bark scribe 14" southerly trunk "T29S R8W S20 CS BT" center of main trunk, bears N.83°W., 29.6' (rec. N.80½°W., 29.6') 1958.
 - 14" now 18" dia. dead Chinquapin, with a fully healed double blaze, bears S.69°W., 12' (agrees with rec.) 1958.
 - 30" now down and rotted Chinquapin near rec. S.66°E., 47'. 1923
 - 26" now 28" dia. 3' high D.Fir stump, with a fully healed single blaze, bears S.49¼°W., 42' (rec. S.49¼°W., 41') 1923.
 - 18" now 29" dia. D.Fir, with a fully healed blaze, bears S.21°E., 14.8' (rec. S.18°E., 14.8') 1958.
 - New - 11" I.Cedar double blazed and scribed "T29S R8W S29 CS BT", bears S.46°W., 38.6'.
Fence corner bears N.45°W., 3'.

BLM Dependent resurvey by Timothy J. Moore & A. Bert Skeesick, Cadastral Surveyors under Group #2097, surveyed Sept. 2004 (DCSO rec. Vol. 55 pg(s) 21283-4)

The cor. of secs. 20, 21, 28, &d 29, perpetuated by the Douglas County Surveyor's Office in 1923, remonumented by the Douglas County Surveyor's Office in 1958, and rehabilitated by the Douglas County Surveyor's Office in 1997, monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd.from which the remains of the original bearing trees

- A fir, 25" dia., bears N.20°E., 34.9 ft., with a healed blaze. (Record, N.22°E., 33.0 ft.)
- A decayed fir stump, size indeterminate, bears S.28½°E., 28.0 ft., with no marks visible. (Rec S.27°E., 31.7 ft)

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and the remains of bearing trees mkd. by the Douglas County Surveyor's Office in 1923

A sawed fir stump, 32" dia., bears S.49½°W., 41.9 ft., with a healed blaze.

A roothole, bears S.72°E., 46.2 ft., with fallen chinquapin trunk, 30" dia., lying alongside, no marks visible.

A sawed fir stump, 32" dia., bears S.49½°W., 41.9 ft., with a healed blaze.

and the remains of bearing trees mkd. by the Douglas County Surveyor's Office in 1958

A fir, 30" dia., bears S.19¼°E., 14.3 ft., with a healed blaze.

A dead chinquapin, 18" dia., bears S.67¼°W., 12.0 ft. with a healed double blaze.

A double trunk madrone, 26" dia., bears N.83°W., 28.8 ft., with scribe marks T29S R8W visible in the bark of southerly trunk and decayed blaze on northerly trunk with no marks visible.

and a bearing tree mkd. by the Douglas County Surveyor's Office in 1997

A cedar, 11" dia., bears S.46¼°W., 38.5 ft., with fragmentary scribe marks visible on a partially healed double blaze.