

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6595)

Set ¼ sec. post, from which
A Laurel 12" dia., bears N.50°E., 10 lks. dist.
A Laurel 15" dia., bears S.40°W., 20 lks. dist.

Art Boyer, Surveyor #1581 - R.H. Gee; R.J. Henrikson - April 1949 - C.S. File 40/192

Set a 4" x 4" x 4 ft. Fir post marked ¼ S28 on N. face and ¼ S33 on S., from which
12" Fir bears N.37°W., 9.0 ft. mkd. ¼ S28 T29S R8W BT 1581
14" Fir bears S.10°E., 18.6 ft. mkd. ¼ S33 T29S R8W BT 1581.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov/Dec. 1966 - C.S. File 54/38-15

Found - Scribed post at ¼ corner, "¼ S28 ¼ S33".
12" now 17" D.Fir N.37°W., 9.0 ft., scribe marks visible, but not legible.
14" now 17" D.Fir S.10°E., 18.6 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
¼ $\frac{S\ 28}{S\ 33}$
1966

Bearing trees in good condition, no new BTs needed.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2196, Surveyed Feb/March 2008 - (DCSO records Vol. 56 Page(s) 22286)

The ¼ sec. cor. of secs. 28 & 33, reestablished by Boyer, perpetuated by the Douglas Co Surveyors Office in 1967, and is accepted as the corner, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above the ground, with brass cap (properly) mkd.
from which bearing trees by Boyer
A fir, 26" dia. bears S.8½°E., 18.1 ft with a healed blaze
A fir, 27" dia. bears N.34¾°W., 9.2 ft with a healed blaze