

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec Cor for 15, 16, 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6592)

Set post cor. secs. 15, 16, 21 and 22, from which
A Chinquapin 10" dia., bears S.80°W., 91 lks. dist.
An Oak 12" dia., bears N.32°W., 64 lks. dist.
A Laurel 12" dia., bears N.70°E., 46 lks. dist.
A Fir 60" dia., bears S.8°E., 10 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-18

Found - Orig. 60" now 66" Fir stump bears S.8°E., 6.6 ft. No scribing found.
12" now 20" Oak snag N.32°W., 42.2 ft., open and find good scribing.
12" now 28" Laurel N.70°E., 30.4 ft., shows old scar. I do not open.
SW. BT would be in logging road.
I find 1" Iron pipe bears N.7½°W., 14.3 ft. May be set for section corner.

Set Brass cap at cor. mkd: County Surveyors Office

T 29 S R 8 W
S 16 | S 15
S 21 | S 22
1958

New BTs- 10" W.Fir bears S.32°E., 120.0 ft. scribed S22 T29S R8W CS BT.
8" Cedar bears N.83°E., 31.7 ft. scribed S15 T29S R8W CS BT.
14" R.Fir bears N.23°E., 67.7 ft. scribed S15 T29S R8W CS BT.
No trees to West.

Fd. OK, Jan. 1995 by K. DeGroot - C.S. File 63/52; M 121-33

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 16995-96)

The Sec. cor., perpetuated and recorded by Byron in 1958, monumented with an iron post 1¼" dia., firmly set, projecting 16" above ground, with brass cap mkd. in 1958 from which the remains of two original bearing trees:

A Madrone 30" dia., bears N.70°E., 46 lks. dist., with healed blaze.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec Cor for 15, 16, 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed Fir stump 65" dia., bears S.8°E., 12 lks. dist., no marks visible. (Rec. 10 lks.)
and bearing trees mkd. by Byron:
A Fir snag 17" dia., bears N.21°E., 103 lks. dist., with scribe marks T29S R8W S15 CS BT visible on open double blaze.
A Cedar 14" dia., bears N.82°E., 49 lks. dist., with healed double blaze.
A grand Fir 20" dia., bears S.33½°E., 180 lks. dist., with healed double blaze.
and new bearing trees:
A Fir 12" dia., bears S.17°W., 44 lks. dist. mkd. T29S R8W S21 BT.
A Fir 8" dia., bears N.18½°W., 24 lks. dist. mkd. T29S R8W S16 BT.

Mark Smalley - January 2000 - C.S. File 65/30-1

Condition Report only
Found - 1958 DCS0 IP BC. Solid in ground.
12" Fir N.18½°W., 16.0 ft., good condition - healed face.
65" Fir Stump S.8°E., 6.6 ft.
26" N.70°E., 30.4 ft. good condition - healed face.
15"- 9' tall fir snag N.21°E., 68.0 axe marks no scribe work,
18" I.Cedar N.82°E., 31.7 ft. good condition - healed face.
20" Fir S.17°W., 29.0 ft. good condition - healed face.
24" Fir S.33½°E., 120.0 ft. good condition - healed face.

FD. BC, 5 BTs & IP by Ken Hoffine - Sept. 2006 - M151-47