

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6594)

Set post cor. secs. 3, 4, 9 and 10, from which
A Fir 30" dia., bears N.70°W., 13 lks. dist.
A Fir 30" dia., bears S.60°W., 24 lks. dist.
An Oak 10" dia., bears N.33°E., 63 lks. dist.
A Laurel 9" dia., bears S.37°E., 56 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-27

Found - Orig. 30" now 36" Fir stump, N.70°W., 8.6 ft., shows good bark scribing "T29S R8W"
Orig. 30" now 40" Fir, S.60°W., 15.8 ft., shows good bark scribing "T29S R8W S BT". This BT has been rebark scribed 10 years ago more or less.
No trace of SE. or NE. BTs.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
S 4 | S 3
S 9 | S 10
1958

I find 3/8" Iron rod, bears N.80°E., 1.9 ft.
New BTs- 7" W.Fir bears S.7½°E., 22.7 ft. scribed S10 T29S R8W CS BT.
11" W.Fir bears N.61°E., 41.1 ft. scribed S3 T29S R8W CS BT.
24" D.Fir bears N.87½°W., 8.0 ft. barks scribe T29S R8W S9 CS, scribed "BT" in wood.

Survey by Bruce A. Shaner - For: U.S. Bureau of Land Management - Aug. 25, 1972 - M 42-67

Found - Brass cap marked by the county in 1958.
Orig. 36" D.Fir, stump, scribes partially visible, bears N.87½°W., 8.1 ft.
Orig. 40" D.Fir, scribes partially visible bears S.60°W., 15.8 ft.
28" D.Fir, bark scribe, bears N.87½°W., 8.1 ft.
16" W.Fir, bears N.61°E., 41.1 ft.
Parts of W.Fir, CS BT, pushed down, found reversed scribes, bears S.9°E., 22.4 ft.
New BT - I scribed 12" W.Fir "T29S R8W S10 BT", bears S.53°E., 26.5 ft.

(Cont. Next Page)

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and Used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 17000)

Corner report by OSHD, Sept. 26, 1986 gives the 40" Fir stump, N.70°W. as S.E. - C.S. File 63/9-30