TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias_____ Description_____
Alias_____ Description_____
Alias_____ Description_____
Alias_____ Description_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page) 6590)

Set ¼ sec. post, from which
A Fir 12" dia., bears N.29°E., 27 lks. dist.
A Fir 7" dia., bears S.68°E., 12 lks. dist.

Art Boyer, Surveyor #1581 - Wit: R.H. Gee; R.J. Henrikson - April 1959 - C.S. File 40/192

Found original Fir BT, S.68°E., 12 lks. mkd. ¼ S plainly.
Also found original BT, N.29°E., 27 lks., tree down.
Marked New BT:
12" Incense Cedar mkd. "¼ S27 BT 1581"
Reset corner with 2 x 3 x 4 Live Oak post mkd. "¼ S27" on N. face and "¼ S34" on S. face.

Douglas Co. Surveyors Office - John M. Powell, and crew - April 1967 - C.S. File 54/38-22

Found - Orig 7" now 16" D.Fir S.68°E. 7.9 ft shows good scar
Orig. 12" Fir, now down and very rotten, N.29°E., 17.8 ft., no scribing visible.
Unrecorded 12" now 14" Cedar N.9½°W., 25.4 ft., scribe visible "¼ S27", very good "BT" scar.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
¼ S 27 / S 34
1967
Bearing trees all in good condition and tagged.
Corner lies 10.0 ft. S. of small spring branch.

Fd. OK, Jan. 10, 1980 by H. Johnstone - M 79-15

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2196, Surveyed Feb/March 2008 - (DCSO records Vol. 56 Page(s) 22282)

The ¼ sec. cor. of secs. 27 & 34, perpetuated by Boyer, subsequently perpetuated by Douglas Co Surveyors Office in 1967, monumented with an iron post, 1¼" dia., firmly set, projecting 9" above the ground, with brass cap (properly) mkd from which the remaining original bearing tree
A fir, 16" dia., bears S.68°E., 7.9 ft., with a burned healed blaze.
and a bearing tree mkd. by Boyer, PE No. 1581

continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A cedar, 19" dia., bears N.10½°W., 25.3 ft., with a healed double blaze.
Corner is located 20 ft. West of a ravine, drains S.40°E.