

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page 6585)

Set ¼ sec. post, from which
A Fir 6" dia., bears N.75°W., 7 lks. dist.
A Laurel 9" dia., bears N.50°E., 18 lks. dist.

Douglas County Surveyors Office - John Powell and crew - C.S. File 54/38-28 - Aug. 7, 1970

Corner searched for, not found.
Two small BTs, probably logged.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - March 1990 - M 101-76

Set 5/8"x48" Iron rod & alum. cap mkd. "¼ 27|26", from which
12" Fir N.15°W., 24.0 ft. scribed ¼ S27 BT.
14" Fir S.56°W., 29.3 ft. scribed ¼ S27 BT.
7" Fir N.83°E., 20.9 ft. scribed ¼ S26 BT.
13" Fir N.65°E., 33.0 ft. scribed ¼ S26 BT.

Found OK by D. Edwards, April 2003 - M142-6

Ken Hoffine - For: Lone Rock Timber Co. - May 2006 - C.S. File 65/58-18

Condition Report only
Found - Iron rod with no cap
¾" iron pipe bears S.30°W., 0.9
16" 7' tall stump with rotten face bears S.68½°E., 33.2, rec. S.65°E., 33.0
19" D.Fir bears S.48°W., 29.5, rec. S.56°W., 29.3 healed face.
16" D.Fir bears N.19¼°W., 24.1, rec. N.15°W., 24.0 healed face.
14" madrone stump with healed face bears N.21¼°E., 7.1, tag reads S.19°E., 8.0 ft., no record.

Note - Lone Rock ran a close loop traverse thru corners (North & south section corners) shown on sketch (in file) to determine bearings & distances for the blazing & painting of property lines.
Corner lies approx. 10 ft. west of dirt road at top of cut bank.
Compass decl. 19½°E.