

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 22, 23, 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6586)

Set post cor. secs. 22, 23, 26 and 27, from which
A Fir 30" dia., bears S.89°W., 50 lks. dist.
A Fir 24" dia., bears S.47°E., 33 lks. dist.
A Laurel 7" dia., bears N.22°E., 50 lks. dist.
A Sugar Pine 8" dia., bears N.11°W., 51 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 10, 1958 - C.S. File 49/100-40

Found - Orig. 20" now 26" rotted snag, S.47°E., 21.8 ft., I open near base and find good scribing "BT"
Orig. 30" now 40" Fir stump S.89°W., 33.0 ft., shows good scar, I do not open.
No trace of other original BTs.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
S 22 | S 23
S 27 | S 26
1958

New BTs- 10" R.Fir bears S.24½°E., 26.5 ft. scribed S26 T29S R8W CS BT.
6" R.Fir bears N.82°E., 4.0 ft. scribed S23 CS BT.
6" Chinquapin, North, 28.0 ft. scribed S22 T29S R8W CS BT.
9" Chinquapin S.65°W., 19.0 ft. scribed S27 T29S R8W CS BT.

Fd. and Used in BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15763)

David Edwards - For: Roseburg Resources - 4/2003 (added 8/28/2024) - M142-6

Found - DCSO BC
12" Chinquapin North 28.0'
12" Fir N.82°E., 4.0'
17" Chinquapin S.65°W., 19.0'
New - 9" Chinquapin S.53°E., 8.4' "S 26 BT"