

PRIMARY CORNER DESCRIPTION Sec. Cor. for Secs. 14, 15, 22 and 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6587)

- 
- Set post cor. secs. 14, 15, 22 and 23, from which
- A Dogwood 10" dia., bears N.80°E., 13 lks. dist.
  - A Chinquapin 12" dia., bears S.8°W., 13 lks. dist.
  - A Chinquapin 12" dia., bears S.25°E., 23 lks. dist.
  - A Chinquapin 12" dia., bears N.24°W., 30 lks. dist.

BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15764)

-----

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29	S R 8	W
S 15		S 14
S 22		S 23
1975		

- from which
- A Fir 6" dia., bears N.72½°E., 46½ lks. dist. mkd. T29S R8W S14 BT.
  - A Fir 4" dia., bears S.50 3/4°E., 21 lks. dist. mkd. X BT.
  - A W.Fir 10" dia., bears S.50°W., 27 lks. dist. mkd. T29S R8W S22 BT.
  - A W.Fir 10" dia., bears N.81½°W., 27½ lks. dist. mkd. T29S R8W S15 BT.

Fd. and Used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 16990)

Ron Quimby - 1/2008 - C.S. File 65/63-5

- 
- Condition report only
- Found - 1975 BLM brass cap
- 16" Fir N.72½°E., 30.7 ft.
  - 12" Fir S.50¾°E., 13.9 ft.
  - 16" W.Fir S.50°W., 17.8 ft.
  - 21" W.Fir N.81½°W., 18.2 ft.