

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec Cor for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6588)

Set post cor. secs. 10, 11, 14 and 15, from which
An Oak 15" dia., bears N.30°W., 58 lks. dist.
An Oak 10" dia., bears S.12°E., 76 lks. dist.
An Oak 8" dia., bears S.35°W., 63 lks. dist.
A Pine 36" dia., bears N.40°E., 81 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-21

Found - W.Oak now 12", S.35°W., 41.6 ft. This tree had been opened several years ago, and plainly visible but badly rotted scribing "T29S R8W S15" can be seen. Badly rotted Pine stump, approx. 40" dia., N.40°E., 53.5 ft. Too far gone to find any scribing. Stump hole and dead Oak shoots, N.30°W., 38.3 ft. No trace of SE. BT found.
15" I.Cedar with "BT" cut in with an axe about 20 years ago, N.35°W., 13.3 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
S 10 | S 11
S 15 | S 14
1958

Blaze and scribe
17" D.Fir S.27½°W., 25.5 ft. mkd. T29S R8W S15 CS BT
15" I.Cedar N.35°W., 13.3 ft. mkd. T29S R8W S10 CS BT.
8" D.Fir S.85°E., 33.3 ft. mkd. T29S R8W S14 CS BT.
13" D.Fir N.27½°E., 45.2 ft. mkd. T29S R8W S11 CS BT.
Fence corner East and South, bears S.18°W., 7 ft.

Fd. and Used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1027, surveyed May 1980/Aug. 1982 - (DCSO records Vol. 44 Page(s) 16992)

Fd. BC and 4 BTs, R. Quimby 2/2008 - C.S. File 65/63-10

James Klein & Michael Erickson - For: Pacific Connector Gas Pipeline Project/Williams - 9/2014 - M166-24A-D & M166-40 A-D

FOUND - 2½" brass cap stamped Co Surveyors Office dated 1958
19" Fir with healed face and tag dated 2/08;
N.28°E., 44.9'. continued next page

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>16" Fir stump 10' tall healed face and tag dated 2/08; S.85°E., - 33.3'</p> <p>23" Fir with healed face and tag dated 5/80; S.25°W., 25.7'</p> <p>25" Cedar with healed face and tag dated 5/80; N.36½°W., 13.3'</p>