

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6587)

Set ¼ sec. post, from which
A Cedar 10" dia., bears S.41°E., 60 lks. dist.
A Laurel 10" dia., bears N.41°E., 27 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-20

Found - Orig. 10" now 26" Cedar snag, S.41°E., 39.6 ft., previously opened, shows good scribing "¼S".
No trace of original NE. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
¼ $\frac{S}{S}$ $\frac{14}{23}$
1958

New BTs- 16" Cedar bears S.58½°W., 17.5 ft. scribed ¼ S23 CS BT.
14" R.Fir bears N.29°E., 27.0 ft. scribed ¼ S14 CS BT.

Fd. and Used in BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15765)

Ron Quimby - 1/2008 - C.S. File 65/63-3

Found - County Surveyors office 1958 brass cap
31" cedar S.58½°W., 17.5 ft.
14" fir stump N.29°E., 27.0 ft.
New - 8" fir N.70°W., 8.0 ft.
8" fir N.52°E., 9.9 ft.
14" cedar S.64°E., 4.2 ft.
All scribed ¼ S BT.