

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Dan Saily - For: Lone Rock Timber Management LLC - Crew:
Trevor Clemo & Brodie Minter - 9/19/2024 - CS File 65/113-49

Found - 1924 GLO brass cap (properly mkd) and iron pipe
26"x4.3' tall D.Fir stump bears N.56°E., 5.7'. 1924
GLO record N.61°E., 6.6'. healed face & BLM tag.
7" D.Fir bears N.21°E. 38.0' 2003 M142-6 rec N.19°E.,
38.0'. Healed face & Roseburg Resources tag.
15" D.Fir bears N.11°W. 53.4' 2003 M142-6 rec N.11°W.
53.6'. Healed face & Roseburg Resources tag.
Unable to locate NW D.Fir BT stump at 1924 GLO or
1997 M127-38 records.

Set - 5/8"x40" iron rod with orange plastic cap marked
LONE ROCK TIMBER 85006PLS bears N.30°19'38"E.,
47.88'. We place a 5½' tall galvanized steel
U-post beside with BT tag. Top of cap is 0.6'
above ground.

5/8"x40" iron rod with orange plastic cap marked
LONE ROCK TIMBER 85006PLS bears S.85°05'20"E.,
97.68'. We place a 5½' tall galvanized steel
U-Post beside with BT tag. Top of cap is 0.8'
above ground.

We place 5½ ft tall galvanized steel U-Posts 2.5'
N.45°W., 2.5'; S.45°W., 2.5'; S.45°E., & 2.5'
N.45°E.

Note - Fd 1924 GLO brass cap and iron pipe as per 1924 GLO
record Vol.14 Pg 6025, leaning slightly to the
South. The top of the monument is 0.3' above a
mound of stone that we raised around the corner.
The monument lies on a west facing slope at the
toe of a logging landing fill slope, approx. 40'
North of the north edge of a newly constructed
rock surface logging landing and 48' west of the
west edge of a rock surface logging road. We
utilized an aluminum nail in the face of Edwards
2003 BT at N.11°W., as per M142-6, to establish
our basis of bearing. BTs were measured with a
TRIMBLE C5 TOTAL STATION to an nail at side
center for distance & at center face for bearing.