

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6581)

Set ¼ sec. post, from which
A Cedar 20" dia., bears S.10°E., 18 lks. dist.
A Fir 24" dia., bears S.21°W., 36 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Oct. 10, 1958 - C.S. File 49/100-41

Found - Orig. 20" now 34" Cedar, S.10°E., 11.9 ft., previously opened, shows parts of good scribing on partly rotted face, "4".
No trace of orig. SW. BT, which would be in creek.
Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 8 W
¼ S 23 | S 24
1958

New BTs- I rescribe 34" Cedar S10°E., 12.7 ft. "¼ S24 CS BT"
32" R.Fir bears S.55°W., 30.2 ft.

Fd. OK, Jan. 10, 1980 by H. Johnstone - M 81-75

Survey by Mark Smalley - For: Kenneth & Hallie Ford - Dec. 1994 - M 121-51

Found - 1958 DCSO brass cap and iron pipe.
34" Cedar S.10°E., 11.9 ft., snag, scribe visible.
32" Fir S.55°W., 30.2 ft., rotten snag.
New BTs- 16" Cedar N.85°E., 63.5 ft. scribed ¼ S BT.
12" Fir N.24°E., 40.2 ft., scribed ¼ S BT.
14" Maple S.43°E., 33.0 ft. scribed ¼ S BT.
10" Cedar S.28°W., 51.3 ft.