

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 620420

PRIMARY CORNER DESCRIPTION SW 1/16 Cor. Sec. 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15780-81)

Point for the SW 1/16 sec. cor. of sec. 13, at intersection with the E. and W. center line.

Set an iron post 28" long, 2½" dia., 20" in the ground, with brass cap marked: SW 1/16 S 13

1975

from which

A Cedar 6" dia., bears N.25°E., 35 lks. dist. mkd. SW 1/16 S13 BT.

A Fir 16" dia., bears S.81°W., 32 lks. dist. mkd. SW 1/16 S13 BT.

Douglas Co. Surveyors Office - Gary L. Langlitz and crew - May 9, 1977 - C.S. File 59/34-9

Found - A 2½" Iron pipe firmly set, extending 8" above ground with standard BLM brass cap attached mkd. in 1975.

A 16" D.Fir alive, with scribing "SW 1/16 S13 BT" visible on unhealed single blaze, bears S.81°W., 21.1 ft.

A 6" now 8" I.Cedar, alive, with scribing "SW 1/16 S13 BT" visible on unhealed single blaze, bears N.22°W., 23.1 ft. (Rec. N.25°E., 23.1 ft.)

We Do Not Remonument.

(Note: At the time of visit by Langlitz, the 1975 BLM survey had not been filed with the county. "Unofficial notes were filed in C.S. File 58/82) V.Laugen, March 1997