TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6580)

Set ¼ sec. post, from which
An Oak 12" dia., bears S.50°W., 40 lks. dist.
A Laurel 12" dia., bears N.40°W., 13 lks. dist.

(Corrective resurvey)- Fred Mensch, U.S. Deputy Surveyor - under date of April 18, 1924 - (DCSO records Vol. 14 Page(s) 6027)

Intersect the point for ¼ sec. cor., located by measurement from the original bearing trees.
At the exact cor. point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ cor., with brass cap marked: ¼ S 24 / S 25 / 1924
from which the original bearing trees:
A Laurel stump, not Oak, bears S.50°W., 40 lks. dist. marks are plain on the log.
A Laurel stump bears N.40°W., 13 lks. dist.
New Bearing trees:
A Cedar 10" dia., bears N.6°E., 7 lks. dist. mkd. ¼ S24 BT.
A Cedar 9" dia., bears S.8°W., 26 lks. dist. mkd. ¼ S25 BT

Fd. OK, Jan. 10, 1980 by H. Johnstone - M 81-75

Fd. and used in BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1454, surveyed Aug. 1988/May 1989 - (DCSO records Vol. 49 Page(s) 18738-39)

Survey by Mark Smalley - For: Kenneth and Hallie Ford - Dec. 1994 - M 121-51

Found - 1924 GLO brass cap and iron pipe.
14" Cedar S.8°W., 17.3 ft., healed.
New BTs- 11" Fir N.17°E., 21.9 ft., scribed ¼ S BT.
11" Cedar S.1°E., 28.7 ft. scribed ¼ S BT.