

TOWNSHIP 29 RANGE 08 POINT IDENTIFIER # 640420

PRIMARY CORNER DESCRIPTION Center S. 1/16 cor. Sec. 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Charles E. Akin, Jr.; James E. Jelley, Cadastral Surveyors and Bruce A. Shaner, RLS #430, under Contract #52500-CT5-1117 - Surveyed June 1973/April 1976 Under Group #'s808; 858; 860, - (DCSO records Vol. 39 Page(s) 15777-78)

Point for the center S 1/16 sec. cor. of sec. 13.
Set an iron post 28" long, 2½" dia., 20" in the ground, with
brass cap marked: C
 S 1/16|S 13
 C
 1975

from which
 A Fir 12" dia., bears N.15°E., 35 lks. dist. mkd. CS 1/16
 S13 BT.
 A Fir 10" dia., bears S.80°W., 49 lks. dist. mkd. CS 1/16
 S13 BT.
Corner is located on spur, slopes NW.

Douglas Co. Surveyors Office - Gary L. Langlitz and crew -
May 9, 1977 - C.S. File 59/34-11

Found - A 2½" Iron pipe, firmly set, extending 8" above
 ground, with standard BLM brass cap attached,
 mkd. in 1975
 A 10" D.Fir with scribing "CS 1/16 S13 BT" visible
 on unhealed single blaze, bears S.78°W., 32.3 ft.
 (Rec. S.80°W., 32.3 ft.)
 A 12" now 13" D.Fir with scribing "C S 1/16 S13 BT"
 visible on unhealed single blaze, bears N.17°E.,
 23.1 ft. (Rec. N.15°E., 23.1 ft.)

*(Note: This 1975 BLM survey was not recorded with the county
at the time of Langlitz's 1977 visit. "Unofficial notes were
filed in C.S. File 58/82) V.Laugen, March 1997*