

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page 6627)

Set ¼ sec. post, from which
A Fir 18" dia., bears N.88°W., 52 lks.
A Fir 30" dia., bears S.58°E, 70 lks.

GL0 resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6633-34)

Intersect at point for ¼ sec. cor. Corner post and one witness tree destroyed. Set a Cedar post 3 ft. long, 4" sq., 24" in the ground mkd. ¼ S33 on W.; and 34 on the E. face, from which
A Hemlock 10" dia., bears S.58°E., 50 lks. mkd. ¼ S34 BT
A Fir, old BT, 24" dia bears N.88°W., 52 lks mkd. ¼ S33 BT

Douglas Co. Surveyors Office - James Byron, Deputy - April 1957 - C.S. File 47/173-1

Found - 30" Fir snag, old blaze opened bear base, good scribing found, N.88°W., 34.3 ft.
Also found 3" x 3" sq. stake at corner mkd. ¼ S.
Set an iron pipe with brass cap at corner mkd.
Coos Co. | Douglas County
 | Surveyors Office
 S 33 | S 34
 | ¼
 | 1957
from which
28" Cedar bears N.85°W., 22.2 ft scribed ¼ S33 CS BT
6" Cedar bears S.20°E., 14.8 ft. scribed ¼ S34 CS BT

Fd. OK, April 1991 - M 113-20
Fd. OK, March 1996 by Hoffine - M 123-59

BLM Dependent resurvey by Joseph J Johnson, Cadastral Surveyor under Group #2864, surveyed Feb. 2017/Oct. 2018 - (DCSO Records Vol. 59 Page(s) 23694-5)

The ¼ sec. cor. of secs. 33 & 34, perpetuated by Byron, in 1957, subsequently perpetuated by Hoffine, in 1995, further perpetuated by Dado in 2015, from orig. evidence no longer in existence monumented with an iron post, 1½" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.
Continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the bearing trees mkd. by Byron
A cedar stump, 23 ins. diam., bears S.25¼°E., 14.2 ft.,
with a healed blaze and aluminum nail driven at the
base on right side center.
A cedar, 32" dia., bears N.83¾°W. 22.5 ft., with illegible
scribe marks visible on partially healed blaze.
and a bearing tree mkd. by person(s) unknown
A fir, 40" dia. bears S.17½°W., 21.6 ft., with an X
chopped in bark at base by Dado.
and an accessory mkd. by Dado
A spike bears N.70°E., 58.2 ft. with a washer mkd COOS
COUNTY SURVEY, driven in the top of a hollow cedar
stump, 44" dia. with an X chopped in bark at base.
and a new reference monument
An iron rod, 30" long, 5/8 in dia., set 27" in the ground
for a reference monument, bears N.76°07'37"E 17.56 ft.
with aluminum cap mkd. RM T29S R9W ¼ S34 17.6 FT TO COR
2017 and an arrow pointing to the cor.