

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6628-29)

-
- Set post cor. secs. 21, 22, 27 and 28, from which
- A Fir 50" dia., bears S.65°E., 98 lks.
 - A Fir 20" dia., bears S.35°W., 12 lks.
 - A Hemlock 15" dia., bears N.20°E., 100 lks.
 - A Hemlock 12" dia., bears N.45°W., 48 lks.

GL0 resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6636)

-
- Intersect at point for sec. cor. Post and one tree gone, two down and stump of fourth witness tree standing, which agree with notes of same furnished by the surveyor general.
- A Hemlock 10" in dia., at point for cor. of secs. 21, 22, 27 and 28, which I mark T29S S22 on the NE.; R9W S27 on SE.; S28 on the SW.; and S21 on the NW. sides with 2 notches on the S. and 3 notches on the E. and, from which
- A Maple 7" dia., bears N.52°E., 68 lks. dist. mkd. T29S R9W S22 BT.
 - A Fir 8" dia., bears S.70°E., 38 lks. dist. mkd. T29S R9W S27 BT.
 - A Fir 9" dia., bears S.70°W., 22 lks. dist. mkd. T29S R9W S28 BT.
 - A Yew 14" dia., bears N.14°W., 46 lks. mkd. T29S R9W S21 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Oct. 13, 1959 - C.S. File 49/100-67

-
- Found - Rooted stump of old Corner Tree, no scribing visible.
- Maple tree, now 15", N.52°E., 44.9 ft. (slope dist.) with old rotted face exposed. Fragments of unmistakable scribing visible.
 - Yew tree, now 16" with face opened, scribing "T29S R9W S21 BT" plainly visible. Yew bears N.11°W., 29.4 ft.
 - The Fir to the SW. is uprooted and nearly completely buried in ground. Did not open.
 - Badly rotted remains of Fir stump, bears S.7°E., 25 ft. No face or scribing visible.

(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At corner, Set Iron pipe with brass cap alongside of old Hemlock stump, mkd: Douglas County Surveyors Office
T 29 S R 9 W
S 21 | S 22
S 28 | S 27
1959

Blaze and scribe new trees:
20" D.Fir S.71°E., 25.9 ft. mkd. T29S R9W S27 CSBT
24" D.Fir N.32°E., 119.0 ft. mkd T29S R9W S22 CSBT

Kris DeGroot - For Silver Butte Timber - 6/2010 - M160-78

Found 1959 DCSO BCIP & accessories per (Ren)
Lat: 43°01'31.995329"N Long. 123°45'41.332149"W

BLM Dependent resurvey by Joseph J Johnson, Cadastral Surveyor under Group #2864, surveyed Feb. 2017/Oct. 2018 - (DCSO Records Vol. 59 Page(s) 23703-4)

The cor. of secs. 21, 22, 27, & 28, perpetuated by Byron, in 1959, monumented with an iron post, 1½" dia., firmly set, projecting 10" above ground with a brass cap (properly) mkd. from which the remains of the BTs mkd. by Porter in 1907

A fir, 32" dia., bears S.70°E., 25.1 ft., with a healed blaze.

A yew snag, split in half, 16" dia., bears N.12°W., 28.6 ft., with illegible scribe marks visible on partially healed blaze. (Record, bears N.14°W., 30.4 ft.)

and the remains of a bearing tree mkd. by Byron

A fir stump, 45" dia., bears N.34¼°E., 124.2 ft., with no marks visible on decayed open blaze

and new bearing trees

A maple, 14" dia., bears N.61½°E., 41.5 ft., mkd. T29S R9W S22 BT.

A maple 9" dia., bears S.63¼°W., 15.0 ft., mkd. T29S R9W S28 BT.

A fir, 35" dia. bears N.15½°W., 16.8 ft., mkd. T29S R9W S21 BT.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument unless a similar marker wa already in place.