

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. S. Champman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 16 Page(s) 6632)

Set ¼ post 4 ft. long, 4" dia., one ft. in ground from which
A Cedar 15" dia., bears N.41°E., 29 lks. dist.
A Hemlock 8" dia., bears S.40°W., 39 lks. dist.

Claude Kerr - March 10, 1960 - C.S. File 51/76

Found one of the original BTs, a Cedar bearing N.41°E., 29 lks., chopped in and found the scribe markings. I rescribed this tree on a new face with ¼ S3 BT.
I set a 3" x 4 ft. Cedar limb as the ¼ corner stake.
New BT - 28" Hemlock was faced and mkd. ¼ S4 BT, bearing S.58°W., 35.7 ft. from ¼ corner.

Douglas Co. Surveyors Office - A. Victor Cangie; James Cook, crew - March 23, 1976 - C.S. File 59/8-11

Found - 15" now 24" Cedar, (orig. NE. BT) already opened. Scribe marks from orig. survey and renewal done by Kerr. Both visible and in different depths in trees. Tree is alive and in fair condition bearing N.41°E., 19.1 ft.
22" Hemlock recorded in 1960 to be 28". I find the recorded bearing and dist. to be in error and change it from S.58°W., 35.7 ft. to S.56°W., 4.2 ft. Tree alive and well, scribing visible.

I found no trace of other BTs or monument.
At corner point established from orig. 15" Cedar, SET a 1" x 30" I.P. with brass cap stamped: Douglas County Surveyor
T 29 S R 9 W
1/4 Corner
S 4 | S 3
1976

New BT - 19" Hemlock bears S.4°W., 17.8 ft. and mkd. ¼ S4 CS BT in a double blaze.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2092, surveyed Sept. 2004 - May 2005 - (DCSO records Vol. 56 Page(s) 22252-3)

The ¼ sec. cor. of secs. 3 and 4, perpetuated by Claude Kerr, in 1960, and remonumented by the Douglas County Surveyors Office in 1976, monumented with an iron post, 1¼" dia., firmly set, projecting 5" above ground, with brass cap (properly) mkd. continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remaining original bearing tree
A cedar, 30" dia., bears N.36°E., 19.1 ft., with scribe marks rescribed by Kerr S30 BT visible on a decayed, partially healed blaze. (Record, N.41°E.)
and remains of a bearing tree mkd. by Kerr
A hemlock snag, 25" dia., bears S.55¼°W., 43.1 ft., with a healed blaze.
and remains of a BT mkd. by the Douglas Co. Surveyors Office
A decayed hemlock snag, 20" dia., bears S.2°W., 17.1 ft., with scribe marks¼ S4 CS BT visible on a partially healed double blaze.
and a new bearing tree
A hemlock, 18" dia., bears S.46½°W., 45.5 ft. mkd.¼ S4 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.