

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 cor. for Sec. 34; & Sec. 3, T30-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 17 Page(s) 7374)

Set ¼ sec. post, from which
A Fir 24" dia., bears S.25°W., 40 lks. dist.
A Fir 12" dia., bears N.18°E., 52 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Oct. 20, 1959 - C.S. 49/100-75

Found - Orig. 24" now 30" Fir snag, S.25°W., 26.4 ft. I open and find good scribing "BT"
No trace of original NE. BT found.

Set Brass cap at cor. mkd: County Surveyors Office
T29S R9W
¼ $\frac{S\ 34}{S\ 3}$
T30S R9W
1959

New BTs- 6" R.Fir bears N.28°E., 18.0 ft. scribed ¼ S34 CSBT.
8" R.Fir bears S.10°W., 14.0 ft. scribed ¼ S3 CS BT.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor and Robert H. Browning, Surveying Technician, under Group #1579 - Surveyed Feb/April 1991 - (DCSO records Vol. 50 Page(s) 19234-35)

The ¼ sec. cor., perpetuated by Byron in 1959, from original evidence no longer in existence, monumented with an iron post 1¼" dia., firmly set, projecting 16" above ground, with brass cap mkd. in 1959, from which a bearing tree mkd. by Byron:
A Fir 13" dia., bears N.28°E., 27 lks. dist., with healed double blaze.
and a new bearing tree:
A Fir 6" dia., bears S.68°W., 17 lks. dist. mkd. X BT.

Survey by Ken Hoffine - For: Lone Rock Timber - March 1996 - M 123-59

Found - 1959 DCSO brass cap in good condition.
6½" D.Fir bears S.67°W., 10.8 ft. (rec. unknown) well healed face and BLM tags.
14" D.Fir bears N.26½°E., 18.8 ft. (Rec. N.28°E., 18 ft.) well healed face and BLM tag.
26" orig. BT, very rotten stump, bears S.24°W., 27.5 ft. (Rec. S.25°W., 26.4 ft.)

(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 cor. for Sec. 34; & S. 3, T30-9

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Corner is 1.5 ft. above ground on steep East facing slope.
190° South of ridge with old skid road and location tag.
(This corner recorded prior to the approved 1991 BLM survey
being recorded, hence the ("rec. unknown") V.Laugen 4/97