

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6621)

Set ¼ sec. post, from which
A Fir 6" dia., bears S.20°W., 4 lks.
A Fir 6" dia., bears N.10°E., 7 lks.

Douglas Co. Surveyors Office - James W. Byron, Deputy - April 1957 - C.S. File 47/173-3

Found 4" x 4" sq. post at corner and both original BTs, now snags. I open SW. BT and find scribing "¼ S BT" and NE. BT scribed "BT".
Set an iron ppe with brass cap at cor. mkd. ¼ S34|S35 T29S R9W County Surveyors Office 1957. From which
20" W.Fir bears N.54½°E., 274.5 ft. scribed ¼ S35 CS BT.
24" Cedar stump N.68°W., 59.4 ft. scribed ¼ S34 CS BT.

Fd. and Used in BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14027-28)

"No new bearing tree available within limits"

BLM resurvey by Wayne L. Rogers Cadastral Surveyor and Garry L. Moore, Surveying Technician, under Group #1516, Surveyed Dec. 1989/March 1990 - (DCSO records Vol. 50 Page(s) 18975)

The ¼ sec. cor., monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground with brass cap mkd. in 1957,
from which the remains of bearing trees mkd. by Byron in 1957:
A W.Fir 29" dia., bears N.54½°E., 416 lks. dist., with scribe marks ¼ S35 visible on partially healed blaze.
A sawed and burned Cedar stump 24" dia., bears N.68°W., 90 lks. dist. with scribe marks ¼ S34 BT visible on open blaze.
and new bearing trees:
A Fir 6" dia., bears N.30¼°E., 14 lks. dist. mkd. ¼ S35 BT.
A Fir 8" dia., bears N.57¼°W., 14 lks. dist. mkd. ¼ S34 BT.

Fd. OK March 1996 by K. Hoffine - M 123-59

continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent retracement by A Bert Skeesick Cadastral Surveyor, Group No. 2300 surveyed Oct. 2007 - (DCSO records 2010 plat & copy of map in Vol. 56 Page(s) 21925)

The ¼ sec cor of secs. 34 & 35, monumented with an iron post, 1½" dia. firmly set, projecting 11" above the ground, with brass cap mkd as reported in 1989-90, from which the remains of BTs mkd by Byron, in 1957, reported by Rogers & Moore

A fir, 28" dia., bears N.54½°E., 274.6 ft., with a healed double blaze.

A sawed and burnt cedar stump, 24" dia., bears N.68°W., 59.4 ft., with scribe marks ¼ S34 CS BT visible on an open blaze.

and the remains of bearing trees mkd. by Rogers, and Moore

A fir, 11" dia., bears N.30¼°E., 9.2 ft., with a healed blaze.

A sawed fir stump, 14" dia., bears N.57¼°W., 9.2 ft. with a healed blaze.

and a new bearing tree

A fir, 6" dia., bears S.81½°W., 103.9 ft., mkd. ¼ S34 BT.
Latitude 43°00'12.90"N. Longitude 123°44'30.56"W.
(NAD 1983 (CORS))

The geodetic position shown hereon was determined by NAVSTAR GPS, utilizing dual frequency, carrier phase GPS receivers, relative to the National Spatial Reference System.