

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6624)

Set ¼ sec. post, from which
A Fir 20" dia., bears S.50°W., 12 lks.
A Laurel 12" dia., bears N.45°E., 28 lks.

GLO resurvey by William M. Porter, Deputy Surveyor, Under Special Instructions dated June 5, 1907, Independent of, but in connection with his contract #768, dated March 8, 1907 - (DCSO records Vol. 16 Page(s) 6638)

Intersect at point for ¼ sec. cor. which is post firmly set, marked as described by the Surveyor General, with bearing tree standing, which also agrees with description furnished, from which post,
A Fir 5" dia., bears N.57°E., 25 lks. mkd. ¼ S23 BT for new witness tree.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Sept. 1959 - C.S. File 49/100-58

Found - Orig. 20" now 40" Fir, S.50°W., 7.9 ft., now down, shows good bark scribing "¼".

No trace of original NE. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 9 W
¼ S22 | S23
1959

New BTs- 12" Cedar bears N.27°E. 94.0 ft. scribed ¼ S23 CS BT
12" W.Fir bears S.29½°W., 71.0 ft. scribed ¼ S22 CS BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14020)

(Found 1959 brass cap, 1 orig. BT, 2 BTs by Byron)
"Add marks BLM 1966 to brass cap".

Fd. OK, Sept. 1996 by J. Minor - M 125-76

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2043, surveyed May/June 2003 - (DCSO rec. Vol. 55 Page(s) 21354-5)

continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The ¼ sec. cor. of secs. 22 and 23, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 8" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
A decayed fir stump, size indeterminate, bears S.50°W., 7.9 ft., with fragmentary axe marks visible. (1966 record, 73.9 ft.; 1855 record, 7.9 ft.)
and the bearing trees mkd. by the Douglas County Surveyor's Office, reported by Jelley
A cedar, 32" dia., bears N.26°E., 94.0 ft., with a healed double blaze.
A fir, 30" dia., bears S.28°W., 70.6 ft., with a healed double blaze.
and bearing trees mkd. by person(s) unknown
A fir, 16" dia., bears N.76°E., 28.2 ft., with scribe marks ¼ S BT visible on a partially healed blaze.
A fir, 17" dia., bears N.26°W., 17.2 ft., with fragmentary scribe marks visible on a partially healed blaze.
Corner is located 2.0 ft. W. of a fence cor. with woven wire fences extending N. and S.