

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6626)

-----  
Set 1/4 sec. post, from which  
A Hemlock 18" dia., bears S.45°E., 71 lks. dist.  
A Fir 48" dia., bears S.6°W., 91 lks.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14024)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 23" in the ground, with brass cap mkd:  
T 29 S R 9 W  
1/4  
S 10 S 11  
1966

from which  
A Hemlock 13" dia., bears N.83°E., 31 lks. dist. mkd. 1/4 S11 BT.  
A Fir 15" dia., bears N.39°W., 18 lks. dist., mkd. 1/4 S10 BT.

Fd. and Used in BLM Resurvey by Jack W. Bowder; John P. Farnsworth; Wayne L. Rogers, Cadastral Surveyors, Group #'s 976; #1000; #996; #1091, surveyed May 1979/Sept. 1982 - (DCSO records Vol. 44 Page(s) 17087-88)

Wayne Rogers - For: The Timber Co. - March 2001 - M136-62 A&B  
-----  
Found - Monument & BTs per 1979-1982 BLM survey.  
New BTs- A 10" dia. Fir bears S.3 1/2°E., 28.7 ft. mkd: 1/4 S11 BT  
A 12" dia. Fir bears S.48°W., 39.2 ft. mkd: 1/4 S11 BT