

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6625)

Set ¼ sec. post, from which
A Fir 20" dia., bears North 64 lks.
A Fir 10" dia., bears S.21°W., 40 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - Sept. 1959 - C.S. File 49/100-59

Found - Orig. 20" now 40" R.Fir, North 42.2 ft., shows good bark scribing "¼S".
Orig. 10" now 26" Fir S.21°W., 26.4 ft., shows scar. I do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 9 W
¼ S 11
S 14
1959

New BTs- 12" R.Fir bears South, 35.9 ft. scribed ¼ S14 CSBT
8" Hemlock bears N.49°W., 2.9 ft. scribed ¼ S11 CS BT.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14029)

(Found 1959 Brass cap; 2 orig. BTs; 2 BTs. by Byron)
"Add marks BLM 1966 to brass cap"

Fd. and Used in BLM Resurvey by Jack W. Bowder; John P. Farnsworth; Wayne L. Rogers, Cadastral Surveyors, Group #'s 976; #1000; #996; #1091, surveyed May 1979/Sept. 1982 - (DCSO records Vol. 44 Page(s) 17084-85)

Fd. OK, Jan. 1984 by E. Bloom - M 95-75

Survey by Clyde E. Mulkins, LS #2006 - May 1, 1988 - C.S. File 63/69-29

Found - 1959 2½" brass cap with 1" I.P. loose in ground from logging operations. Cap also stamped with BLM 1966.

Orig. BT, 44" D.Fir stump with orig. lower blaze visible bark scribed "BT" bears North 42.5 ft. to center.

(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Orig. BT, 32" D.Fir visible bark face, no scribes bears S.18°W., (Orig. S.21°W.) 27.8 ft. to center (Byron 26.4 ft.)
1959 BT, 17" D.Fir green with top out. Upper and lower faces healed over, bears South 35.0 ft. to center.
9" Hemlock 1959 BT, root collar very rotten, not used. (Rec. N.49°W., 3.0 ft.)
Dug new hole, set found monument in 1959 position with 12" above ground. BTs re-tagged and painted fluorescent orange.

Gary Smithers - For: Moore Mill & Lumber Co. - July/Aug. 2000 - M 135-53

Found - 2½" brass cap on iron pipe marked per rec. M 95-75B with red steel fence post 1 ft. south of corner.
44" D.Fir stump North 42.5 ft. bark scribe has been cut out with chain saw & metal roofing placed over stump.
35" D.Fir S.18°W., 26.4 ft. with BT tag.
17" D.Fir south 35.0 ft. rotting away with BT tag.
9" Hemlock N.49°W., 3.0 ft. rotting away.
New BTs- 10' W.Fir S.18°E., 30.6 ft. to spike side center scribed T29 R9 ¼ S14 BT with BT tag.
21" W.Fir S.29°W., 27.4 ft. to spike side center scribed T29 R9 ¼ S14 BT with BT tag.

Greg Lang - 9/15/2004 - C.S. File 65/20-10

Found - DCS0 brass cap
11" W.Fir bears S.17°E., 31'
10½" Fir bears S.32°W., 44.7' scribed "¼ S14 BT"
7" Fir bears N.83½°W., 82.45' scribed "¼ S11 BT"
6" Fir bears N.46°E., 28.55' scribed "¼ S11 BT"
Note - We set spikes in the base of all bearing trees; bearings to the trees were measured with a total station & are based on the original GLO survey. Corner lies on a southerly slope approx. 100' north of Deep Creek.

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor & Robert H. Browning, Survey Tech under Group #2158, surveyed April/May 2007 - (DCS0 records Vol 55 Pages 21495-4)

The ¼ sec. cor. of secs. 11 and 14, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 14" above the ground with brass cap mkd.
continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

COUNTY SURVEYORS OFFICE
T 29 S R 9 W
S 11
S 14
BLM 1/4
1966 1959

from which the remains of an original bearing tree
A sawed fir stump, 46" dia., bears North, 42.2 ft., with
a healed blaze.
and the remaining bearing tree mkd. by Smither, in 2000
A fir, 12" dia., bears S.17°E., 31.0 ft., with fragmentary
scribe marks visible on a partially healed blaze.
and bearing trees mkd. by Lang, in 2004
A fir, 8" dia., bears N.46¼°E., 28.5 ft., with fragmentary
scribe marks visible on a partially healed blaze.
A fir, 11" dia., bears S.31¾°W., 44.8 ft., with
fragmentary scribe marks visible on a partially healed
blaze.
A fir, 9" dia., bears N.83½°W., 82.1 ft., with fragmentary
scribe marks visible on a partially healed blaze.

James Klein & Richard Kitz - For: Pacific Connector Gas
Pipeline Project/Williams - Sept. 2014 - M166-18 A-C &
revised map M166-43 A

Found - 2½" brass cap on 1" pipe stamped County Surveyor
Office 1959
BTs - 12" Fir with healed face & tag dated 09/04 N.46°E.,
28.55'
12.5" Fir with healed face & tag dated 08/00
S.18°E., 30.6'
13" Fir with visible scribe & tag dated 09/04
S.32°W., 44.7' to nail.

3