

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6618)

Set post cor. secs. 323, 24, 25 and 26, deposited charred stake and raised mound with trench as per instructions.

J.W. Cole, Deputy Co. Surveyor - Wit: P.D. Wolford; G.A. MacHenry - Aug/Sept. 1920 - Vol. 3 Pages 70-71; Field Book 48 Page 10+; C.S. File 6/17

Set Iron pipe 1" x 36" with 2" Iron pipe. No evidence of old corner. No suitable trees near.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14007)

The Sec. cor., perpetuated and recorded by Cole in 1920, monumented with an iron pipe 1½" dia., firmly set, extending 18" above the ground. Cole did not state how he determined this corner point, but he does state that no evidence of the original corner was found. This corner position is very near the proportionate position, and is therefore accepted.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 29 S R 9 W

S 23 S 24

S 26 S 25

1966

from which

A Fir 35" dia., bears N.28°E., 124 lks. dist. mkd. T29S R9W S24 BT.

A Fir 25" dia., bears S.15°E., 23½ lks. dist. mkd. T29S R9W S25 BT.

A Fir 22" dia., bears S.35°W., 26 lks. dist., mkd. T29S R9W S26 BT.

No bearing tree available to the NW. within limits.

Reset Iron pipe alongside iron post.

From this point, the SE. corner of a wood frame house, bears N.24°E., 0.25 chs. dist., dimensions 28½ x 39 ft., long side bears N. and S.