

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6618)

Set post cor. secs. 13, 14, 23 and 24, from which
A Fir 10" dia., bears N.23°W., 35 lks.
A Fir 15" dia., bears S.50°E., 59 lks.
A Fir 24" dia., bears S.50°W., 112 lks.
A Fir 30" dia., bears N.80°E., 67 lks.

Douglas Co. Surveyors Office, James W. Byron, Deputy - April 1957 - C.S. File 47/173-2

Found 3/4" Iron pipe at corner and all BTs. The SW. is standing, has been opened years ago, no scribing visible. Was probably bark scribed. The NE. and SE. show bark scribing. The NW. Bt has old blaze, under. The NW., SE., and NE. BTs down. All four BTs check for bearing and distance.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R 9 W
S 14 | S 13
S 23 | S 24
1957

from which
12" W.Fir, S.58°E., 26.7 ft. scribed S24 T29S R9W CS BT.
12" W.Fir, S.70°W., 22.8 ft. scribed S23 T29S R9W CS BT.
10" Cedar, N.9°E., 57.4 ft. scribed S13 T29S R9W CS BT.
12" W.Fir, N.56°W., 62.8 ft. scribed S14 T29S R9W CS BT.

Fd. OK, Jan. 1984 by E. Bloom - M 95-75

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14009-10)

(found 1957 brass cap, four orig. BTs, and 4 BTs by Byron)
"Add marks BLM 1966 to brass cap."

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2008, surveyed June/July 2002- (DCSO rec. Vol. 54 Page(s) 21054-5)

The cor. of secs. 13, 14, 23, & 24, monumented with an iron post, 1" dia., firmly set, projecting 7" above ground, (with an iron pipe, 3/4" dia., projecting 9" above ground alongside), with brass cap (properly) mkd.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remains of the original bearing trees
A roothole, bears N.80°E., 44.2 ft., with decayed trunk, size and species indeterminate, lying alongside, no marks visible. (Record, fir)
A roothole, bears S.50°E., 38.9 ft., with decayed trunk, size and species indeterminate, lying alongside, no marks visible. (Record, fir)
A roothole, bears S.50°W., 73.9 ft., with decayed trunk, size and species indeterminate, lying alongside, no marks visible. (Record, fir)
A roothole, bears N.23°W., 23.1 ft., with decayed trunk, size and species indeterminate, lying alongside, no marks visible. (Record, fir)
and BTs mkd. by Byron, in 1957, and reported by Jelley
A cedar, 29" dia., bears N.9°E., 57.8 ft., healed blaze.
A fir, 31" dia., bears S.60°E., 27.1 ft., with healed double blaze.
A fir, 29" dia., bears S.67°W., 22.8 ft., with healed double blaze. (Record S.73°W.)
A fir, 21" dia., bears N.56°W., 62.7 ft., with healed double blaze.

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2043, surveyed May/June 2003 - (DCSO rec. Vol. 55 Page(s) 21341-2)

The cor. of secs. 13, 14, 23, & 24, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above ground, (with an iron pipe, ¾" dia., projecting 9" above ground alongside) with brass cap (properly) mkd.
from which the remains of the original bearing trees
A root hole bears N.80°E., 44.2 ft., with decayed trunk, size indeterminate, lying alongside, with no marks visible.
A root hole bears S.50°E., 38.9 ft., with decayed trunk, size indeterminate, lying alongside, with no marks visible.
A root hole bears S.50°W., 73.9 ft., with decayed trunk, size indeterminate, lying alongside, with no marks visible.
A root hole bears N.23°W., 23.1 ft., with decayed trunk, size indeterminate, lying alongside, with no marks visible.
and bearing trees mkd. by the Douglas County Surveyor's Office, reported by Jelley
A cedar, 29" dia., bears N.9°E., 57.8 ft., with a healed blaze.
continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 31" dia., bears S.60°E., 27.1 ft., with a healed double blaze.
A fir, 29" dia., bears S.67°W., 22.8 ft., with a healed double blaze. (Record, S.73°W.)
A fir, 21" dia., bears N.56°W., 62.7 ft., with a healed double blaze.
Corner is located N. 83° E., 0.8 ft. dist., of a fence corner, fences extend south and west.

Fd as per record 5/2019 by D. Edwards M175-61