

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; S. 36, T28-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

**ON THE COUNTY LINE - CHECK WITH COOS COUNTY
FOR POSSIBLY MORE INFORMATION**

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page 6615)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.5°E., 15 lks. dist.
A Fir 15" dia., bears S.73°W., 7 lks. dist.

BLM Resurvey by William W. Glenn, Cadastral Surveyor, under Group #'s 350 and 420, surveyed April/June 1959 - (DCSO records Vol. 30 Page(s) 12847)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T 28 S
R 9 W
¼ S 36
S 1
T 29 S
1959

from which

A W.Fir 9" dia., bears N.29 3/4°W., 34½ lks. dist. mkd. ¼ S36 BT.

A W.Fir 8" dia., bears S.30°E., 55½ lks. dist. mkd. ¼ S1 BT.

Corner falls in the head of a ravine, draining S.

Douglas Co. Surveyors Office - M. Lenora Ladig; Karen Cheney, crew - May 13, 1976 - C.S. File 59/15-3

Found - 1959 GLO brass cap buried approx. 2 ft. under cut of old cat road as mkd. in 1959.

A 1" I.P., 1 ft. above ground.

A 9" now 15" W.Fir bears N.29 3/4°W., well healed.

Found no trace of SE. BT.

Placed sign post 3 ft. East of corner.

New BT - 7" W.Fir bears S.6°E., 24.3 ft. scribed "¼ S1 CW BT" in double blaze. (No larger trees to the South)

Corner lies approx. 1000 ft. North of Lang Creek Rd. in trees above second large clear cut.

Fd. OK by K. Hoffine, Nov. 1999 - M133-58

continued next page

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; S. 36, T28-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Coos County Surveyors Office - Michael Dado, Surveyor - Crew:
Matthew Martin & Bill Hales - 12/2/2014 - C.S. File 65/87-24

Found - 3¼" brass cap, on a 2½" iron pipe, buried 0.9' deep, leans slightly to the South, in good condition and solid in the ground. Note: We find a 1" iron pipe, 0.1' South. The cap is oriented N12°E. Monument falls on the SE edge of an old cat road running NE/SW. Steel fence post and sign stands 3' East of BCIP. 1959

Found hole in ground with G.Fir bark around hole, N.26°W., 23.43' to center. Fd tag on ground. 1959
19" G.Fir, S.10°E., 25.15' to right side center. We find a healed blaze and a Douglas County tag in place. We paint the face and a band around the tree in blue. GOOD CONDITION. 1976

20" G.Fir stump, N.78°W., 17.66' to spike at left side center. We chop an "X" in the stump, paint the "X" in blue and place a yellow Coos County tag. FAIR CONDITION. 1999

Note: These existing BTs have aluminum nails in the face and side centers, but no other marks.

New BT- A 12" D.Fir, S.62°W., 25.60' to a spike at right side center. We blaze and scribe "¼ S1 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag.

A 9" D.Fir stump, 3' tall, N.72°E., 15.69' to a spike at right side center. We chop an "X" in the face. We paint the "X" and the top of the stump in blue and attach a yellow Coos County tag.

Warren Knight Staff Compass - declination 17°E