

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T29-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6574)

Set post cor. secs. 18, 19, 13 and 24, from which
A W.Oak 30" dia., bears S.85°W., 554 lks. dist.
A W.Oak 36" dia., bears N.72°E., 952 lks. dist.
A W.Oak 20" dia., bears S.52°E., 1754 lks. dist.
A Fir 15" dia., bears N.87½°W., 567 lks. dist.

J.W. Cole, Deputy - P.D. Wolford, chain - Sept. 13, 1920 -
Field Book 48 Pg. 44

Set rock 6" x 8" x 14" under ground mkd. with +, from which
A Rock 6" x 8" x 14" bears East, 17 ft.
A Rock 6" x 8" x 14" bears West 22 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo
Godfrey; S. Bilow, crew - Sept. 1958 - C.S. File 49/100-13

Found Offset stones as recorded by Cole in 1920:
6"x8"x14", East 17 ft. and 6"x8"x14", West 22 ft.
Both stones now covered.
I do not search for corner stone.
Set brass cap alongside stone to West, mark brass cap "Wit.
Cor. 22.0 ft. East to S13 S18 S19 S24 R9W R8W County
Surveyors Office 1958".
New BT - 16" W.Oak bears S.43½°E., 320.2 ft. scribed T29S R8W
S19 CS BT.
No suitable trees near to SW.; NW.; or NE.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s
350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34
Page(s) 14000-01)

The Sec. cor., perpetuated and recorded by Cole in 1920,
monumented with a stone, 14x8x6 ins., set 12" below the
surface of a gravelled county road, 30 lks. wide, bears N.
and S. Cole did not record on what basis he determined this
corner point, however, it is harmoniously related with
existing original corners to the N. and W., has long been
recognized as the corner by local surveyors, and is accepted
as the best available evidence of the position of the
original corner, from which a bearing tree and a reference
monument marked by Byron in 1958:
(Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T29-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An Oak 18" dia., bears S.43 3/4°E., 461 lks. dist. with healed double blaze.

An iron pipe 1" dia. firmly set, extending 8" above ground and in a N. and S. fence line, bears West, 33½ lks. dist., with brass cap mkd. County Surveyors office Wit. Cor. 11 ft. East to Sec. Cor. R9W S13 S18 S19 S24 R8W T29S 1958.

Add marks BLM 1966 to brass cap.

No new bearing trees available within limits.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart, crew - Wit: Sam Bright, landowner. - April 13, 1981 - C.S. File 61/19-38

Found - Both of Coles' 1920 reference stones buried in their original location. Dist. & brg. between two stones match record exactly. 1958 DCSO Wit. Cor. had been knocked out and was at Mr. Harold Bright's house.

16" now 19" W.Oak, in a group of 9 Oaks) with well healed double blaze, bears S.43½°E., 304.8 ft. (Rec. 320.2 ft.) from sec. cor. location.

All original bearing trees are gone.

Set boat spike in asphalt concrete near center of road for sec. corner. Corner was set on line at proper distance between 1920 stones.

Set a Brass cap Wit. Cor., set 16 ft. East of sec. corner mkd. "Wit. Cor. 16 ft. West to sec. cor. R9W R8W S13 S18 S24 S19 T29S 1981 Douglas County Surveyor." Brass cap was set 1 ft. West of easterly stone, 1½ ft. West of old fence, and is 8" out of ground.

New Accessories:

48" Cedar with scribed "T29S R9W S24 CS BT" in single blaze bears S.89°W., 496.9 ft. to face.

Power Pole #1C 17 11, bears N.11½°W., 114.5 ft.

Survey marker sign bears East 17.5 ft.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Nov. 4, 1992 - C.S. File 64/35-2

Found - Orig. and stone monument from Cole, NOT found. Magnetic evidence indicates boat spike in asphalt roadway is in place but is now buried below surface shallowly.

All bearings and distances measured from above mentioned boat spike. (Cont. Next Page)

TOWNSHIP 29 RANGE 09 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T29-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

No evidence of 2 rocks from Cole found. West rock would fall under roadway and East rock not dug for, in order to not disturb brass cap and I.P. from 1981.

No evidence of witness corner found, from 1958.

A 16" Oak now a 20" dia., breast high W.Oak with fully healed double blaze, in tight group of nine Oaks, now all fallen and soon to be removed, bears S.43½°E., 304.8 ft. (1981)

From 1981, A Brass cap/IP bearing object (erroneously called a witness corner), a bearing tree and a power pole bearing object are all found.

A 2½" dia., brass cap mkd. "Douglas County Surveyor" on a 1¼" outside dia. I.P., is firmly set, protruding 8" above ground and bears East, 16.0 ft. (as per record). A survey marker sign bears 1½ ft. East from brass cap monument.

A 48" now 52" dia., breast high Cedar with fully healed single blaze, bears S.88½°W., 498.7 ft. (Rec. S.89°W., 496.9 ft. to face.)

A power pole # 1C 17 11, bears N.12¼°W., 113.5 ft. (Rec. N.11½°W., 114.5 ft., probably to older power pole. Found power pole appears new.)

New BTs- An 18" dia., breast high Maple scribed "X BT" on a double blaze, bears N.05'E., 407.6 ft.

A 32" dia. breast high W.Oak scribed "T29S R8W S19 CS BT" on a double blaze, S.34½°E., 709.8 ft.

Monument is near center of North bound lane of Westside Rd. (Co. Rd. #129) in Camas Valley just South from curve in road where direction changes from E-W to N-S direction.

Land Mark Surveying - Bart Heichel - 2/5/2025 - 2025-0005 A
Found ok per record - Magnetic reading in asphalt (held)

3